



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOW GARNET			Ref: CS/ASM22011186/Uvp3e2 Date: 15/11/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHD 8608D	Veh. Inspected	SMD 2300X
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S2M04E75	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	07/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MINI COOPER S HB (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WMWSV32090T672756	Colour	PINK / PURPLE
	Odometer	101120 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	05/11/2022	Inspection Date	09/11/2022
	Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	