

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011190/EVP3Q2**Date:** 21/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00154832102

**Claimant Vehicle No :** SNF7240E **Insured Vehicle No :** GBH282L

Date of Loss: 04/11/2022 Nature of Claim: TP Claim No: SNM22D207994/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNF7240E**

Make & Model: BMW 116D, 1.5 D 5DR HATCH LED (A) Engine No: HIDDEN

Reg. Date: 17/06/2022 (Man. Year: 2022) Chassis No: WBA7K120807K77611

Colour: White Odometer: 4349 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,357.04	5,040.09	1,316.95	20.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,332.00	5,922.00	2,410.00	28.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,689.04</b>	<b>10,962.09</b>	<b>3,726.95</b>	<b>25.37</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>1,175.12</b>	<b>876.97</b>	<b>298.15</b>	<b>25.37</b>
<b>Nett Amount (S\$)</b>	<b>15,864.16</b>	<b>11,839.06</b>	<b>4,025.10</b>	<b>25.37</b>

**INSPECTION**

Date of Assignment: 08/11/2022

Date Inspected: 08/11/2022 Inspected At: Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2023)
Parts:	144	BMW 116D 1.5 D 5DR HATCH LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF7240E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*TRUNK LID	Dented	1,257.95 FS	*1,257.95 FS
3	1		*REAR BUMPER CARRIER	Bent	446.10 FS	*446.10 FS
4	1		*REAR BUMPER BOTTOM TRIM PANE	Crushed	259.15 FS	*259.15 FS
5	1		*MOUNT FOR CO	Not Necessary	67.15 FS	*- FS
6	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	163.55 FS	*- FS
7	1		*REAR BUMPER REAR TOP (MSP/MP)	Dented	1,088.30 FS	*1,088.30 FS
8	1		*LETTERING 116I	Necessary	65.60 FS	*65.60 FS
9	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
10	1		*PLAQUE 74MM	Necessary	72.85 FS	*72.85 FS
11	1		*BOOT LID /TAILGATE PUSH BOTTON (REK)	Necessary	38.75 FS	*38.75 FS
12	1		*REAR WINDOW GREEN (ESG)	Broken	567.15 FS	*567.15 FS
13	8		*HOOK AND LOOP FASTENER	Necessary	20.00 FS	*20.00 FS
14	1		*REAR BUMPER HEAT INSULATION	Not Necessary	62.75 FS	*- FS
15	1		*LEFT TRUNK LID PANEL TRIM	Cut	40.10 FS	*40.10 FS
16	1		*RIGHT PANEL TRIM	Cut	40.10 FS	*40.10 FS
17	1		*LOWER TRUNK LID TRIM PANEL	Cut	417.30 FS	*417.30 FS
18	1		*TRUNK LID SEALING	Not Necessary	131.25 FS	*- FS
19	1		*BMW ADVANCED CAR EYE 2.0	Not Necessary	892.25 FS	*- FS
20	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
21	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
22	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
23	2		*EXPANDING NUT	Necessary	5.70 FS	*5.70 FS
24	1		*3M S/F PREMIUM REAR WINDSCREEN	Necessary	252.34 FS	*252.34 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	6,357.04	5,040.09
--------------------	----------	----------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	0.00
2	TO CONDUCT WATER LEAK TESTS	New	75.00	0.00
3	TO VACUUM AND CLEAN CAR INTERIOR IN ORDER TO RETRIEVE ALL THE POSSIBLE SHATTERED GLASS DEBRIS AND SHARDS CAUSED BY THE ACCIDENT	New	250.00	250.00
4	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	150.00	150.00
5	TO REPLACE REAR BUMPER ,BOOT LID AND TO KNOCK OUT DENTED AREA	New	2,550.00	1,700.00
6	TO RESPRAY REAR BUMPER AND BOOT LID	New	1,923.00	1,827.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
8	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	545.00
9	TO CONDUCT WATER LEAK TESTS	New	75.00	71.00
10	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
11	TO VACUUM INTERIOR OF BROKEN GLASS DEBRIS	New	177.00	0.00
12	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
13	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR FUNCTION	New	177.00	168.00
14	TO REPLACE IN CAR CAMERA INCLUDING TO PROGRAM AND CHECK FOR FUNCTION	New	450.00	427.00
15	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,332.00</b>	<b>5,922.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >