

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 8760C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PROTERCTOR ,L.RR. WHEEL ARCH (SN) (CONSISTENT)	SCRATCHED	140.92	140.92
1	PANEL COMP ,L.RR DOOR(SN)(CONSISTENT)	TO REPAIR SEE LABOUR	701.32	-
1	TAPEL.RR.DOOR PROTECTOR (SN)(CONSISTENT)	NECESSARY	19.35	19.35
1	SUNDRIES (SN)(CONSISTENT)	NECESSARY	110.00	30.00
			971.59	190.27
	<u>LABOUR</u>			
	RESET VEHICLE SMART ENTRY SYSTEM.		650.00	580.00
	STRAIGHTEN ALIGN RR DOOR INCLUDING FITTINGS INCLUSIVE OF THE REPAIR OF PANEL COMP ,L.RR DOOR.		700.00	650.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS .		600.00	520.00
			1,950.00	1,750.00
	GRAND TOTAL		2,921.59	1,940.27

RECOMMENDED COST OF REPAIRS 1,940.27	RECOMMENDED COST OF REPAIRS			1,940.27
--------------------------------------	-----------------------------	--	--	----------

Report Ref No. CC4/ASM22011196/Rpa3

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

/mon!

HO LEONG CHUAN

Automotive Assessor