12/19/22, 10:05 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI22011207/KNCQ2

**Date:** 19/12/2022

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MN000207

Claimant Vehicle CLICETOIL SINGER AND CLICETOIL SINGER AND

No: Insured Vehicle No: SLS8950M

Date of Loss: 31/10/2022 Nature of Claim: TP Claim No: M2206312

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC5721J

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2H10264

Reg. Date: 13/09/2021 (Man. Year: 2020) Chassis No: JTDKB3FU603092471

Colour: Metallic Pearl White/Red Odometer: 92738 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Wanli 9 mm Rear Left Side: Sailun 6 mm
Front Right Side: Wanli 9 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,195.07	1,507.77	5,687.30	79.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	1,105.00	3,995.00	78.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,295.07	2,612.77	9,682.30	78.75
+ GST 7.00/7.00% (S\$)	860.65	182.89	677.76	78.75
Nett Amount (S\$)	13,155.72	2,795.66	10,360.06	78.75

**INSPECTION** 

Date of Assignment: 10/11/2022

Trans-Cab Services Pte Ltd (HQ)

Date Inspected: 08/11/2022 Inspected At: 2 Ang Mo Kio Street 63

Singapore 569111

Singapore 509 i

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/19/22, 10:05 AM Adjuster Report

Different 1 cents -Finalise confirm amount: \$2,612.78

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Dec 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC5721J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY,FRONT DOOR,RH	Repair	1,300.70 FL	*- FL
2	1		*FRAME SUB-ASSY,FRONT DOOR OUTSIDE HANDLE,RH	Serviceable	193.50 FL	*- FL
3	1		*HANDLE ASSY,FRONT DOOR,OUTSIDE RH	Serviceable	390.60 FL	*- FL
4	1		*MOTOR ASSY,POWER WINDOW REGULATOR,RH	Serviceable	926.00 FL	*- FL
5	1		*WEATHERSTRIP,FRONT DOOR OPENING TRIM,RH	Serviceable	321.10 FL	*- FL
6	1		*HINGE ASSY,FRONT DOOR,LOWER RH	Repair	110.60 FL	*- FL
7	1		*HINGE ASSY,FRONT DOOR,UPPER RH	Repair	97.50 FL	*- FL
8	1		*REGULATOR SUB-ASSY,FRONT DOOR WINDOW,RH	Serviceable	238.30 FL	*- FL
9	1		*TAPE,BLACK OUT,NO.2 FRT RH	Not Necessary	43.50 FL	*- FL
10	1		*TAPE,BLACK OUT,NO.1 FRT RH	Not Necessary	13.30 FL	*- FL
11	1		*TAPE,BLACK OUT,NO.3 FRT RH	Not Necessary	26.30 FL	*- FL
12	1		*MIRROR ASSY,OUTER REAR VIEW,RH	Serviceable	1,436.60 FL	*- FL
13	1		*RIM	Serviceable	1,900.10 FL	*- FL
14	1		*HUBCAP	Serviceable	211.50 FL	*- FL
15	1		*FENDER SUB-ASSY,FRONT RH	Bent	977.80 FL	*977.80 FL
16	1		*EMBLEM,SIDE PANEL RH	Necessary	54.60 FL	*54.60 FL
17	1		*LINER,FRONT FENDER,LH	Cracked	210.30 FL	*210.30 FL
18	1		*COVER,FRONT BUMPER	Mtg Cracked	521.00 FL	*521.00 FL
19	1		*STAY SUB-ASSU,FRONT BUMPER,RH	Serviceable	47.50 FL	*- FL
20	1		*BRACKET,FRONT BUMPER SIDE,RH	Serviceable	59.30 FL	*- FL
21	1		*FRT FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS
22	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
23	1		*DOOR STICKER TRANSCAB	Necessary	100.00 FS	*60.00 FS
24	1		*DOOR TRIM CLIP	Not Necessary	75.00 FS	*- FS
25	1		*DOOR WEATHERSTRIP CLIP	Not Necessary	80.00 FS	*-FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.	1		
				Sub Total (S\$)	9,465.10	1,948.70
			- List Item Discount on L Item	s 25.00/25.00% (S\$)	2,270.03	440.93
				Total Parts (S\$)	7,195.07	1,507.77

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	400.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	660.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labour Cost (S\$)		5,100.00	1,105.00
	Report was unsubmitted during this pri	int-out.		

< END OF ESTIMATES >