

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22011211/AVCE2**Date:** 02/03/2023**REFERENCE**

Insured/Claimant: YEO YING PENG (YANG YINGPING)

Policy No: 2100472838

Date of Loss: 02/11/2022

Nature of Claim: OD Claim No: 3350530743SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLH810U**

Make & Model: AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A)

Engine No: CZC551007

Reg. Date: 29/06/2016 (Man. Year: 2016)

Chassis No: WAUZZZ8V0GA155389

Colour: White

Odometer: 87476 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$65,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,800.00	2,547.44	6,252.56	71.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,702.00	1,242.00	1,460.00	54.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,502.00	3,789.44	7,712.56	67.05
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	11,202.00	3,489.44	7,712.56	68.85
+ GST 8.00/8.00% (S\$)	896.16	279.16	617.00	68.85
Nett Amount (S\$)	12,098.16	3,768.60	8,329.56	68.85

INSPECTION

Date of Assignment: 09/11/2022

Date Inspected: 08/11/2022

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,146.00 FS	*1,716.80 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	175.00 FS	*139.60 FS
3	4		*FRONT BUMPER PULL STRAP - LOWER	Not Necessary	231.00 FS	*- FS
4	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	71.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	122.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cut	765.00 FS	*612.00 FS
7	1		*RADIATOR GRILLE COVER	Not Necessary	109.00 FS	*- FS
8	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
9	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	93.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	63.00 FS	*- FS
13	1		*HORN SIGNAL HIGH TONE - RH	Not Necessary	213.00 FS	*- FS
14	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	183.00 FS	*- FS
15	1		*HEADLIGHT - RH	Not Necessary	2,810.00 FS	*- FS
16	1		*LIFT CYLINDER - RH	Not Necessary	211.00 FS	*- FS
17	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
18	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
19	1		*RADIATOR AIR GUIDE - RH	Not Necessary	28.00 FS	*- FS
20	1		*RADIATOR AIR GUIDE SEAL - RH OUTER	Not Necessary	9.00 FS	*- FS
21	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	14.00 FS	*- FS
22	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
23	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	8,800.00 2,547.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	900.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,702.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >