

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22011213/ANCE2**Date:** 02/08/2023**REFERENCE**

Insured/Claimant:	ROLAND SCHWINN	Policy No:	7210011404	
Date of Loss:	06/11/2022	Nature of Claim:	OD	Claim No: 7906183290SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX7901Z		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC22632
Reg. Date:	29/01/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF36M1057657
Colour:	White	Odometer:	8811 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$162,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,303.00	18,361.68	21,941.32	54.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,172.00	8,372.00	6,800.00	44.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	55,475.00	26,733.68	28,741.32	51.81
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	55,075.00	26,333.68	28,741.32	52.19
+ GST 8.00/8.00% (S\$)	4,406.00	2,106.69	2,299.31	52.19
Nett Amount (S\$)	59,481.00	28,440.37	31,040.63	52.19

INSPECTION

Date of Assignment:	09/11/2022		
Date Inspected:	08/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,308.00 FS	*1,846.00 FS
2	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	132.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Cracked	242.00 FS	*193.60 FS
4	1		*FRONT BUMPER LOWER GRILLE COVER PLATE	Not Necessary	58.00 FS	*- FS
5	2		*FRONT BUMPER GRILLE - LH / RH	Not Necessary	248.00 FS	*- FS
6	1		*FRONT BUMPER END PLATE	Not Necessary	212.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Cut	426.00 FS	*340.80 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	N/S Cracked	342.00 FS	*136.40 FS
9	1		*RADIATOR GRILLE	Cracked	1,594.00 FS	*1,275.20 FS
10	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	271.00 FS	*216.80 FS
11	1		*RADIATOR GRILLE COVER CAP	Cracked	47.00 FS	*36.88 FS
12	1		*RADIATOR GRILLE BRACKET	Not Necessary	46.00 FS	*- FS
13	1		*RADIATOR GRILLE SECURING PLATE	Not Necessary	37.00 FS	*- FS
14	1		*FRONT 360 CAMERA	Not Necessary	1,264.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	114.00 FS	*91.20 FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	974.00 FS	*778.80 FS
17	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	86.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Deformed	137.00 FS	*109.60 FS
19	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
20	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
21	3		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	797.00 FS	*- FS
22	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
23	1		*SET FRONT BUMPER WIRING	Cut	750.00 FS	*600.00 FS
24	1		*HORN HIGH TONE - LH	Not Necessary	154.00 FS	*- FS
25	1		*HORN LOW TONE - RH	Not Necessary	146.00 FS	*- FS
26	2		*HORN BRACKET - LH / RH	Not Necessary	50.00 FS	*- FS
27	1		*FRONT FENDER - LH / RH	N/S Buckled	2,890.00 FS	*1,156.00 FS
28	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	196.00 FS	*- FS
29	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	78.00 FS	*- FS
30	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	520.00 FS	*- FS
31	2		*FRONT WHEEL HOUSING LINER COVER - LH / RH	Not Necessary	36.00 FS	*- FS
32	2		*FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH / RH	Not Necessary	44.00 FS	*- FS
33	1		*BONNET	Buckled	3,695.00 FS	*2,956.00 FS
34	2		*BONNET HINGE - LH / RH	Bent	162.00 FS	*128.96 FS
35	1		*BONNET ATTACHMENT PARTS	Not Necessary	309.00 FS	*- FS
36	2		*BONNET STRIKER - LH / RH	Not Necessary	246.00 FS	*- FS
37	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	31.00 FS	*24.24 FS
38	2		*BONNET LOCK - LH / RH	Not Necessary	455.00 FS	*- FS
39	1		*BONNET SOUND ABSORBER	Not Necessary	244.00 FS	*- FS
40	1		*BONNET RELEASE ELEMENT	Not Necessary	65.00 FS	*- FS
41	1		*BONNET RELEASE LEVER	Not Necessary	16.00 FS	*- FS
42	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
43	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
44	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
45	2		*BONNET LOCK CABLE COVER - LH / RH	Not Necessary	92.00 FS	*- FS
46	1		*PLENUM CHAMBER COVER	Not Necessary	144.00 FS	*- FS
47	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	264.00 FS	*210.40 FS
48	1		*HEADLIGHT - LH / RH	N/S Cracked	11,904.00 FS	*4,761.60 FS
49	1		*HEADLIGHT HEAT SINK	Not Necessary	870.00 FS	*- FS
50	1		*HEADLIGHT POWER MODULE	Not Necessary	850.00 FS	*- FS
51	1		*HEADLIGHT HOSE - LH	Not Necessary	28.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	2		*LIFT CYLINDER - LH / RH	Damaged	462.00 FS	*184.40 FS
53	1		*LIFT CYLINDER HOSE	Not Necessary	92.00 FS	*- FS
54	1		*LIFT CYLINDER WASH WATER RESERVOIR	Not Necessary	240.00 FS	*- FS
55	1		*LOCK CARRIER	Cracked	1,412.00 FS	*1,129.60 FS
56	1		*A/C CONDENSER	Dented	605.00 FS	*483.60 FS
57	1		*RADIATOR ADDITIONAL COOLER	Bent	984.00 FS	*786.80 FS
58	1		*RADIATOR	Not Necessary	1,093.00 FS	*- FS
59	6		*READY-MIX COOLANT	Necessary	297.00 FS	*237.12 FS
60	2		*RADIATOR AIR GUIDE - LH / RH	N/S Cracked	86.00 FS	*34.08 FS
61	1		*RADIATOR AIR GUIDE - UPPER / LOWER	Upper Cracked	96.00 FS	*37.84 FS
62	1		*AIR INTAKE COVER - UPPER	Not Necessary	64.00 FS	*- FS
63	1		*AIR INTAKE COVER - LOWER	Not Necessary	59.00 FS	*- FS
64	1		*AIR INTAKE COVER - CENTER	Not Necessary	21.00 FS	*- FS
65	2		*FRONT WHEEL COVER - LH / RH	Necessary	566.00 FS	*452.00 FS
66	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
67	1		*SUNDRIES	Necessary	400.00 FS	*74.72 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	40,303.00	18,361.68
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,600.00	1,600.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	3,000.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDERS	New	4,500.00	1,650.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			15,172.00	8,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >