

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011214/RPA3Q2**Date:** 19/04/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002889997
Claimant Vehicle No :	SLK5322M	Insured Vehicle No :	YP4307J
Date of Loss:	04/11/2022	Nature of Claim:	TP
		Claim No:	202222007946

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK5322M		
Make & Model:	HONDA CITY, 1.5 SV CVT (A)	Engine No:	L15Z14113413
Reg. Date:	19/01/2017 (Man. Year: 2016)	Chassis No:	MRHGM6660HP000392
Colour:	Black	Odometer:	111750 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	806.35	308.85	497.50	61.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	2,265.00	1,525.00	40.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,596.35	2,573.85	2,022.50	44.00
+ GST 7.00/7.00% (S\$)	321.74	180.17	141.57	44.00
Nett Amount (S\$)	4,918.09	2,754.02	2,164.07	44.00
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,077.02		

INSPECTION

Date of Assignment:	09/11/2022	
Date Inspected:	12/12/2022	Inspected At: Kah Motor Co Sdn Bhd (alexandra) (HQ) 255 Alexandra Road Singapore 159937
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2023)
Parts:	143	HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK5322M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*FACEFR.BUMPER	Repair	344.85 FS	*- FS
3	1		*CLIP ,BUMPER	Not Necessary	17.25 FS	*- FS
4	1		*SPACERL.FR BUMPER SIDE	Not Necessary	7.80 FS	*- FS
5	1		*PANEL COMPL.FR.FENDER	Bent	257.85 FS	*257.85 FS
6	1		*FENDER ASSYL.FR.INNER	Not Necessary	57.60 FS	*- FS
7	10		*CLIP ,INNER FENDER	Necessary	21.00 FS	*21.00 FS
Total Parts (\$\$)						806.35 308.85

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	280.00	250.00
2	REMOVE & RENEW FR L FENDER & BUMPER	New	1,950.00	975.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,560.00	1,040.00
Gross Labour Cost (S\$)			3,790.00	2,265.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >