

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22011216/UYA3Q2**Date:** 08/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0005172_01

Claimant Vehicle No : FBK847S **Insured Vehicle No :** SNH1456D

Date of Loss: 01/11/2022 Nature of Claim: TP Claim No: MFL2022D0008382

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK847S**
 Make & Model: HONDA CB400X, 399cc Engine No: NC47E1005674
 Reg. Date: 13/03/2015 (Man. Year: 2014) Chassis No: NC471005625
 Colour: White Odometer: 103367 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 160/60 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,630.90	5,018.00	10,612.90	67.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	700.00	480.00	40.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,810.90	5,718.00	11,092.90	65.99
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	16,810.90	4,500.00	12,310.90	73.23
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
+ Other Costs (S\$)		150.00		
Nett Liability (S\$)		4,770.00		

INSPECTION

Date of Assignment: 09/11/2022

Date Inspected: 09/11/2022 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Jan 2023)	
Parts:	N/A	HONDA CB400X 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK847S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Not Necessary	280.00 FL	*- FL
2	1		*FRONT SIDE COVER - L/H	Cut	550.00 FL	*299.00 FL
3	2		*FORK INNER TUBES	Not Necessary	1,160.00 FL	*- FL
4	2		*FORK OUTER TUBES	Not Necessary	1,180.00 FL	*- FL
5	1		*FORK UNDER BRACKET	Not Necessary	420.00 FL	*- FL
6	1		*FORK UPPER BRACKET	Not Necessary	310.00 FL	*- FL
7	1		*FRONT RIM SHAFT	Not Necessary	182.00 FL	*- FL
8	1		*HANDLE-BAR	Bent	395.00 FL	*250.00 FL
9	1		*SET HANDLE BAR END	N/S Cut	180.00 FL	*30.00 FL
10	1		*SET HAND-GRIP	Not Necessary	96.00 FL	*- FL
11	1		*SIDE MIRRORS	N/S Broken	320.00 FL	*80.00 FL
12	1		*FRONT SIGNALS	N/S Cut	380.00 FL	*68.00 FL
13	1		*CLUTCH LEVER	Scratched	350.00 FL	*115.00 FL
14	1		*FRONT FOOTREST BRACKETS	N/S Bent	650.00 FL	*160.00 FL
15	1		*GEAR PEDAL	Cut	220.00 FL	*140.00 FL
16	1		*REAR FOOTREST	Cut	150.00 FL	*80.00 FL
17	1		*REAR FOOTREST BRACKET	Cut	275.00 FL	*160.00 FL
18	1		*EXHAUST ASSY	Not Necessary	2,450.00 FL	*- FL
19	1		*EXHAUST PROTECTOR	Cut	188.00 FL	*80.00 FL
20	1		*SIDE STAND	Cut / Bent	145.00 FL	*145.00 FL
21	1		*MAIN STAND	Not Necessary	195.00 FL	*- FL
22	1		*REAR RIM	Bent	1,200.00 FL	*800.00 FL
23	1		*REAR RIM SHAFT	Cut	190.00 FL	*80.00 FL
24	1		*REAR RIM BEARING	Necessary	100.00 FL	*80.00 FL
25	1		*REAR RIM BRAKE DISC	Not Necessary	680.00 FL	*- FL
26	1		*REAR SWING ARM	Dented / Bent	980.00 FL	*980.00 FL
27	1		*REAR FENDER	Distorted	250.00 FL	*165.00 FL
28	1		*REAR FENDER INNER COVER	Cracked	210.00 FL	*140.00 FL
29	1		*REAR FENDER INNER BRACKET	Bent	380.00 FL	*150.00 FL
30	1		*REAR SIGNALS	N/S Cracked	380.00 FL	*68.00 FL
31	1		*REAR NUMBER PLATE LAMP	Cracked	185.00 FL	*70.00 FL
32	1		*FRONT FOOTRESTS	N/S Cut	280.00 FL	*80.00 FL
33	1		*SET NUMBER PLATE	Rear Bent	38.00 FS	*10.00 FS
34	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
35	2		*FORK OIL SEALS	Not Necessary	78.00 FS	*- FS
36	1		*SET STEERING CONE	Not Necessary	150.00 FS	*- FS
37	1		*REAR BOX	Dented	580.00 FS	*480.00 FS
38	1		*REAR BOX BRACKET	Bent	220.00 FS	*180.00 FS
39	1		*REAR SIDE BOX	Cut	250.00 FS	*150.00 FS
40	1		*REAR TYRE (\$200.00) (50%) (LOCAL PURCHASE)	Punctured	385.00 FS	*100.00 FS
41	1		*SET ENGINE CRASH BAR	Bent / Cut	480.00 FS	*300.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,122.00	5,440.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,491.10	422.00
Total Parts (\$\$)					15,630.90	5,018.00
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO RE-ALIGN BODY FRAME	New	500.00	300.00
3	TO PROVIDE LABOUR	New	600.00	400.00
Gross Labour Cost (S\$)			1,180.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >