

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22011218/UPA3Q2**Date:** 19/02/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002451400
<b>Claimant Vehicle No :</b>	SJN1184D	<b>Insured Vehicle No :</b>	SME6039U
Date of Loss:	06/11/2022	Nature of Claim:	TP
		Claim No:	202222007980

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJN1184D</b>	Engine No:	Z6749665
Make & Model:	MAZDA 3, 1.6 SP LUX (A)	Chassis No:	JM6BK106280443939
Reg. Date:	03/02/2009 (Man. Year: 2008)	Odometer:	185391 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,321.30	1,494.00	4,827.30	76.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,010.00	990.00	49.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,321.30</b>	<b>2,504.00</b>	<b>5,817.30</b>	<b>69.91</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	8,321.30	2,000.00	6,321.30	75.97
<b>+ GST 7.00/7.00% (S\$)</b>	582.49	140.00	442.49	75.97
<b>Nett Amount (S\$)</b>	<b>8,903.79</b>	<b>2,140.00</b>	<b>6,763.79</b>	<b>75.97</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,442.00</b>		

INSPECTION

Date of Assignment:	08/11/2022	
Date Inspected:	08/11/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 Feb 2023)	
<b>Parts:</b>	N/A	MAZDA 3 1.6 SP LUX (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJN1184D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,255.80 F	*- FL
2	1		*BOOTLID REAR LOGO	Not Necessary	65.80 F	*- FL
3	1		*BOOTLID MAZDA EMBLEM	Not Necessary	52.00 F	*- FL
4	1		*BOOTLID 3 EMBLEM	Not Necessary	45.00 F	*- FL
5	1		*BOOTLID SKYACTIVE EMBLEM	Not Necessary	68.00 F	*- FL
6	1		*BOOTLID WEATHERSTRIP	Not Necessary	291.40 F	*- FL
7	1		*REAR BUMPER	Dented / Deformed	1,215.10 F	*975.00 FL
8	2		*REAR BUMPER TOW COVERS	Not Necessary	50.00 F	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Repair	745.20 F	*- FL
10	2		*REAR BUMPER REFLECTORS	Not Necessary	150.00 F	*- FL
11	2		*REAR BUMPER SIDE RETAINERS	Necessary	130.00 F	*130.00 FL
12	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
13	1		*REAR BUMPER LICENCE PLATE LAMP	Not Necessary	108.00 F	*- FL
14	1		*SET REAR BUMPER LOWER SKIRTING	Torn	600.00 F	*425.00 FL
15	1		*REAR END PANEL	Repair	635.00 F	*- FL
16	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
17	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
18	1		*REAR LICENCE PLATE	Necessary	50.00 FS	*30.00 FS
19	1		*SET REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>6,321.30</b>	<b>1,810.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	0.00	316.00
<b>Total Parts (S\$)</b>	<b>6,321.30</b>	<b>1,494.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	60.00
5	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	150.00	0.00
6	TO SPRAY RUST PROOFING	New	100.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	400.00
8	TO PUTTY & SPRAY PAINTING	New	800.00	480.00
<b>Gross Labour Cost (S\$)</b>			<b>2,000.00</b>	<b>1,010.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >