

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011219/UPA3Q2**Date:** 16/01/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002790578-01
Claimant Vehicle No :	SLC4596M	Insured Vehicle No :	SMM9886D
Date of Loss:	06/11/2022	Nature of Claim:	TP
		Claim No:	202222007951

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC4596M	Engine No:	LEB5075186
Make & Model:	HONDA VEZEL, 1.5 X HYBRID CVT (A)	Chassis No:	RU31125191
Reg. Date:	16/05/2016 (Man. Year: 2016)	Odometer:	229357 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,284.04	1,273.60	7,010.44	84.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	1,280.00	2,230.00	63.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,794.04	2,553.60	9,240.44	78.35
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	11,794.04	2,000.00	9,794.04	83.04
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
Nett Liability (S\$)		2,200.00		

INSPECTION

Date of Assignment:	08/11/2022	Zoom Autowerks Pte Ltd (HQ)
Date Inspected:	08/11/2022 Inspected At:	130 Bedok Reservoir Road, Eunos Spring, #08-1339
Estimated Period of Repair:	4.0 days	Singapore 470130

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC4596M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	121.80 FL	*- FL
2	1		*REAR TAILGATE	Repair	1,287.60 FL	*- FL
3	2		*REAR TAILGATE DAMPERS	Not Necessary	331.60 FL	*- FL
4	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	225.00 FL	*- FL
5	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	32.00 FL	*- FL
6	2		*REAR TAILGATE LAMPS	Not Necessary	570.00 FL	*- FL
7	1		*REAR TAILGATE LOCK	Not Necessary	269.50 FL	*- FL
8	1		*REAR TAILGATE LOCK CATCH	Not Necessary	55.00 FL	*- FL
9	1		*REAR TAILGATE LOGO	Not Necessary	40.30 FL	*- FL
10	1		*REAR TAILGATE RUBBER	Not Necessary	227.00 FL	*- FL
11	1		*REAR TAILGATE VEZEL EMBLEM	Not Necessary	56.20 FL	*- FL
12	1		*REAR TAILGATE HYBRID EMBLEM	Not Necessary	62.50 FL	*- FL
13	2		*REAR TAILLAMPS	Not Necessary	1,390.00 FL	*- FL
14	1		*REAR END PANEL	Repair	585.80 FL	*- FL
15	1		*REAR END PANEL INNER GARNISH	Not Necessary	160.50 FL	*- FL
16	1		*SET REAR KEYLESS SENSOR	Not Necessary	189.50 FL	*- FL
17	1		*REAR BUMPER	Dented / Deformed	950.60 FL	*762.00 FL
18	2		*REAR BUMPER -SIDE	Not Necessary	450.60 FL	*- FL
19	2		*REAR BUMPER BRACKETS	Not Necessary	97.00 FL	*- FL
20	1		*REAR BUMPER LOWER GARNISH	Warped	325.00 FL	*280.00 FL
21	2		*REAR BUMPER REFLECTORS	Not Necessary	303.80 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	101.80 FL	*- FL
23	1		*REAR EXHAUST SILENCER	Not Necessary	840.30 FL	*- FL
24	2		*REAR EXHAUST MOUNTINGS	Not Necessary	49.00 FL	*- FL
25	2		*REAR FENDER WHEEL ARCH GARNISHES	Not Necessary	601.40 FL	*- FL
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*40.00 FS
28	1		*REAR BUMPER TOP STEP CHROME	Bent	350.00 FS	*200.00 FS
29	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,148.80	1,482.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,864.76	208.40
Total Parts (\$\$)	8,284.04	1,273.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	0.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	120.00	0.00
7	TO APPLY UNDERCOATING	New	150.00	0.00
8	PANEL BEATING	New	1,400.00	450.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	700.00
Gross Labour Cost (S\$)			3,510.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >