

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS22011220/DNY3Q2**Date:** 22/11/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

**Claimant Vehicle No :** GBJ5117M**Insured Vehicle No :** SMJ6363G

Date of Loss: 04/11/2022

Nature of Claim: TP

Claim No: 2022 22007941/FR

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ5117M**

Make &amp; Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD2853233

Reg. Date: 08/05/2019 (Man. Year: 2019)

Chassis No: JTFHT02P500249034

Colour: Silver

Odometer: 136957 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,890.70	3,468.77	7,421.93	68.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	1,790.00	2,540.00	58.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,220.70</b>	<b>5,258.77</b>	<b>9,961.93</b>	<b>65.45</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,220.70</b>	<b>4,000.00</b>	<b>11,220.70</b>	<b>73.72</b>

INSPECTION

Date of Assignment: 09/11/2022

Date Inspected: 09/11/2022 Inspected At:

Goh Lee Hwa Automobile Pte Ltd (HQ)  
Block 5033 Ang Mo Kio Industrial Park 2 #01-255  
Singapore 569536

Estimated Period of Repair: 5.0 days

**Adjuster:** BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 22 Nov 2022)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ5117M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent / Dented	2,182.90 F	*1,855.30 FL
2	2		*REAR BOOT HINGER	Not Necessary	136.20 F	*- FL
3	2		*REAR BOOT ABSORBER	Not Necessary	599.60 F	*- FL
4	1		*REAR BOOT INNER LOCK	Not Necessary	519.40 F	*- FL
5	1		*REAR BOOT INNER BOARD	Not Necessary	490.50 F	*- FL
6	10		*REAR BOOT BOARD CLIPS	Not Necessary	60.00 F	*- FL
7	1		*REAR BOOT LOGO	Necessary	69.10 F	*69.10 FL
8	1		*REAR BOOT HIACE STICKER	Necessary	68.30 FS	*10.00 FS
9	1		*REAR BOOT 1250KG STICKER	Necessary	58.50 FS	*10.00 FS
10	1		*REAR BOOT WEATHERSTRIP	Serviceable	399.80 F	*- FL
11	1		*REAR LAMP	N/S Cut / O/S Not Necessary	796.40 F	*398.20 FL
12	1		*REAR LAMP INNER PANEL	Not Necessary	465.10 F	*- FL
13	1		*REAR LAMP HOUSING PANEL	Not Necessary	422.80 F	*- FL
14	1		*REAR BUMPER	Cracked	659.50 F	*496.40 FL
15	1		*REAR BUMPER RETAINER	Mtg Cracked	69.30 F	*69.30 FL
			(N/S)			
16	1		*REAR BUMPER CATCH	Not Necessary	120.30 F	*- FL
17	1		*SET REAR BUMPER PARKING SENSOR	Damaged	509.40 FS	*150.00 FS
18	1		*REAR FENDER LH	Dented	1,286.50 F	*1,286.50 FL
19	1		*REAR FENDER CORNER GARNISH	Cut / Bent	86.10 F	*86.10 FL
20	1		*REAR FENDER INNER CORNER PANEL	Not Necessary	486.50 F	*- FL
21	1		*REAR FENDER AIR DUST GARNISH	Deformed	110.80 F	*110.80 FL
22	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
23	1		*REAR END PANEL OUTER	Repair	583.10 F	*- FL
24	1		*REAR INNER END PANEL	Not Necessary	690.60 F	*- FL
25	1		*8 PAX STICKER	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,890.70</b>	<b>4,561.70</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	1,092.93
<b>Total Parts (\$\$)</b>	<b>10,890.70</b>	<b>3,468.77</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
2	TO REMOVE & REFIT FLOORBOARD	New	220.00	0.00
3	TO REMOVE & REFIT ALL WIRING	New	180.00	30.00
4	TO WELDING ,KNOCKING STRAIGHTENING REPAIR & RENEW & ALL ACCIDENT AFFECTED AREA	New	1,800.00	800.00
5	TO RESPRAY PAINTING ON INNER & OUTER PARTS & ALL ACCIDENT AFFECTED AREA	New	1,800.00	800.00
6	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	150.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>4,330.00</b>	<b>1,790.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >