

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011223/UYA3Q2**Date:** 11/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070107041-02
Claimant Vehicle No :	SMK2491R	Insured Vehicle No :	GBK4090G
Date of Loss:	09/11/2022	Nature of Claim:	TP
		Claim No:	4621113381SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK2491R		
Make & Model:	HONDA CITY, 1.5 SV CVT (A)	Engine No:	L15Z16206866
Reg. Date:	01/04/2019 (Man. Year: 2019)	Chassis No:	MRHGM6660KT000629
Colour:	Blue	Odometer:	71106 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,027.40	2,742.56	10,284.84	78.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	2,470.00	2,360.00	48.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,857.40	5,212.56	12,644.84	70.81
+ GST 7.00/7.00% (S\$)	1,250.02	364.88	885.14	70.81
Nett Amount (S\$)	19,107.42	5,577.44	13,529.98	70.81
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,079.44		

INSPECTION

Date of Assignment:	09/11/2022	
Date Inspected:	09/11/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	885.10 F	*528.40 FL
2	1		*BOOTLID REAR LOGO	Serviceable	38.80 F	*- FL
3	1		*BOOTLID CITY EMBLEM	Serviceable	35.20 F	*- FL
4	1		*BOOTLID IVTEC EMBLEM	Serviceable	36.50 F	*- FL
5	1		*BOOTLID OUTER CHROME MOULDING	Not Necessary	366.90 F	*- FL
6	2		*BOOTLID REFLECTORS	Scratched / Cracked	850.00 F	*320.00 FL
7	2		*BOOTLID HINGES	Not Necessary	210.00 F	*- FL
8	1		*BOOTLID INNER LOCK	Twisted	165.00 F	*106.80 FL
9	1		*BOOTLID LOCK STRIKER	Not Necessary	60.00 F	*- FL
10	1		*BOOTLID WEATHERSTRIP	Twisted	166.80 F	*166.80 FL
11	1		*BOOTLID INNER TRIM	Not Necessary	288.90 F	*- FL
12	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	39.00 F	*- FL
13	1		*REAR BUMPER	Dented	785.60 F	*463.70 FL
14	2		*REAR BUMPER LOWER SIDE GRILLES	Grazed	176.00 F	*130.00 FL
15	2		*REAR BUMPER SIDE RETAINERS	Necessary	60.00 F	*60.00 FL
16	1		*REAR BUMPER LOWER CENTRE GRILLE	Cut	145.80 F	*92.50 FL
17	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
18	1		*REAR END PANEL	Badly Dented	445.10 F	*385.00 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	221.30 F	*168.50 FL
20	1		*REAR EXHAUST	Not Necessary	688.10 F	*- FL
21	1		*REAR EXHAUST MOUNTING	Not Necessary	30.00 F	*- FL
22	2		*TAILLAMPS	Cracked	890.00 F	*570.00 FL
23	2		*TAILLAMP HOUSING PANELS	Repair	570.00 F	*- FL
24	1		*REAR FLOOR PANEL	Repair	1,066.30 F	*- FL
25	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	422.60 F	*- FL
26	2		*REAR FENDERS	Repair	1,690.40 F	*- FL
27	2		*REAR FENDER INNER TRIMS	Not Necessary	576.00 F	*- FL
28	2		*REAR FENDER UNDER SHIELDS	Not Necessary	90.20 F	*- FL
29	1		*REAR WINDSCREEN MOULDING	Not Necessary	68.80 F	*- FL
30	1		*REAR BUZZLE SENSOR	Cracked	85.00 F	*85.00 FL
31	1		*REAR ANTENNA SENSOR	Serviceable	105.00 F	*- FL
32	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
33	1		*SET REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
34	1		*REAR LICENCE PLATE	Serviceable	50.00 FS	*- FS
35	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
36	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
38	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
39	1		*BOOTLID TOP SPOILER	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,027.40	3,365.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	623.14
Total Parts (\$\$)	13,027.40	2,742.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	0.00
6	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
7	TO CONDUCT CHASSIS ALIGNMENT	New	380.00	0.00
8	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
9	TO SPRAY RUST PROOFING	New	180.00	60.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	1,000.00
11	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,200.00
Gross Labour Cost (S\$)			4,830.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >