

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9188H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	TORN	586.18	586.18
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT FENDER RH	BENT	1,111.93	1,111.93
1	FRT BUMPER SIDE RETAINER RH	DEFORMED	90.75	90.75
1	FRT BUMPER FOG LAMP RH	NOT NECESSARY	920.00	-
1	FRT FENDER EMBLEM RH	NECESSARY	86.50	86.50
1	HEADLAMP ASSY RH	NOT NECESSARY	2,735.28	-
1	FRT RH WHEEL RIM	DENTED	1,570.55	1,570.55
	LESS 25% DISCOUNT		-1,780.80	-866.98
			5,342.39	2,600.93
	NETT ITEMS			
1	REAR DOOR APPS LOGO (N)	CUT	80.00	80.00
1	FRT DOOR COMFORT LOGO (N)	CUT	75.00	75.00
	LESS 10% DISCOUNT		-	-15.50
			155.00	139.50
	SPECIAL NETT ITEMS			
1	FRT ADVERTISEMENT LOGO -FENDER (SN)	CUT	100.00	100.00
1	ADVERTISEMENT LOGO -FRT DOOR (SN)	сит	100.00	100.00
1	ADVERTISEMENT LOGO -REAR DOOR (SN)	CUT	100.00	100.00
1	ADVERTISEMENT LOGO -REAR FENDER (SN)	CUT	100.00	100.00
			400.00	400.00
	<u>LABOUR</u>			
	PANEL BEAT.		1,150.00	525.00
	SPRAYPAINT.		1,600.00	1,500.00
	CHECK WIRING .		50.00	30.00
	TUFF KOTE.		50.00	30.00
			2,850.00	2,085.00
	GRAND TOTAL		8,747.39	5,225.43

Report Ref No. NS/INC22011224/Tvcq2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22011224/Tvcq2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser