



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8462L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RADIATOR GRILLE	CRACKED	1,409.10	1,409.10
1	FRT BUMPER	TO REPAIR SEE LABOUR	481.10	-
1	FRT BUMPER MOULDING CENTRE UPPER	CUT	368.50	368.50
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER CENTRE GRILLE	NOT NECESSARY	318.80	-
	LESS 20% DISCOUNT		-519.90	-359.92
			2,079.60	1,439.68
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT BUMPER .		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK ALL LIGHTING.	NOT NECESSARY	60.00	-
			760.00	600.00
	GRAND TOTAL		2,839.60	2,039.68
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,039.68

Report Ref No. NS/INC22011225/Tncq2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.