

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7222P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	DEFORMED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,768.30	-
1	REAR BUMPER SIDE BRACKET RH	NOT NECESSARY	55.80	-
1	RR WHEEL HUB CAP RH	CRACKED	346.40	346.40
1	FRT DOOR MIRROR ASSY RH	DISTORTED	1,391.70	1,391.70
1	REAR FENDER SHIELD RH	NOT NECESSARY	173.60	-
1	DELTA GARNISH RH	NOT NECESSARY	42.80	-
1	FRT PILLAR UPPER COVER	NOT NECESSARY	89.60	-
1	ARM ASSY -RR TRAILING ARM RH	BENT	265.40	265.40
1	WHEEL ASSY -ALUMINIUM (BLACK)	BENT	1,124.20	1,124.20
	LESS 20% DISCOUNT		-1,147.84	-721.82
			4,591.36	2,887.28
	SPECIAL NETT ITEMS			
1	REAR TYRE RH (70%) (SN)	PUNCTURE	216.00	151.20
1	REAR FENDER ADVERTISEMENT STICKER RH (SN)	CUT	100.00	100.00
			316.00	251.20
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		1,050.00	525.00
	SPRAY PAINTING CHARGE.		1,000.00	600.00
	REMOVE/REFIX REVERSE SENSOR .		60.00	30.00
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX UPHOLSTERY & CUSHION RR.	NOT NECESSARY	120.00	-
			2,350.00	1,155.00
	GRAND TOTAL		7,257.36	4,293.48

Report Ref No. NS/INC22011227/Tncq2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,450.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22011227/Tncq2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**