

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22011228/Rvp3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 30/11/2022 SINGAPORE 068811 ATTN: LOH CYNTHIA Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SMF 4279B **SHB 3147K** Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S2M04EAF Excess (\$) 0.00 **LOH CYNTHIA Assign Date** 09/11/2022 Assign From **Vehicle Particulars & Condition** 2. **HYUNDAI ELANTRA AD 1.6** Make & Model 1591 C.C **GLS** Engine No. **HIDDEN** Year of Reg. 2018 Chassis No. KMHD841CMJU762445 Colour **GREY** 77274 KM IN ORDER Odometer Steering **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General **Conditions of Tyres** 3. Size Make **Balance** 195/65 R15 YOKOHAMA 6 mm R/H Front Tyre YOKOHAMA L/H Front Tyre 195/65 R15 6 mm R/H Rear Tyre 195/65 R15 YOKOHAMA 6 mm 195/65 R15 YOKOHAMA L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. 5. **General Information Accident Date** 28/10/2022 **Inspect Date / Time** 14/11/2022 (01:07 PM) YAP MOTOR REPAIR SERVICE Survey held at BLK 7 SIN MING IND EST SEC C #01-80 & 82 SINGAPORE 575642 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22011228/Rvp3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

3 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser