

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011230/UPA3Q2**Date:** 15/02/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	P000019111
Claimant Vehicle No :	SMM9886D	Insured Vehicle No :	SNH1420G
Date of Loss:	06/11/2022	Nature of Claim:	TP
		Claim No:	202222007956/SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM9886D	Engine No:	FB20Y306062
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No:	JF1SJ5KC5GG073503
Reg. Date:	15/09/2016 (Man. Year: 2016)	Odometer:	90677 km
Colour:	Blue		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R17	Rear Tyre Size:	235/55 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,863.16	4,633.14	10,230.02	68.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	2,900.00	1,270.00	30.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,033.16	7,533.14	11,500.02	60.42
Approved Total (Overridden) (S\$)		5,700.00		
Nett Amount (S\$)	19,033.16	5,700.00	13,333.16	70.05
+ Car Rental (8.0 x S\$150.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,902.00		
Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment:	08/11/2022	Zoom Autowerks Pte Ltd (HQ)
Date Inspected:	08/11/2022 Inspected At:	130 Bedok Reservoir Road, Eunos Spring, #08-1339
Estimated Period of Repair:	7.0 days	Singapore 470130

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Feb 2023)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM9886D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	982.00 FN	*- FN
2	1		*FRONT BONNET CHROME MOULDING	Not Necessary	180.40 FN	*- FN
3	1		*FRONT BONNET LOCK	Not Necessary	115.00 FN	*- FN
4	2		*FRONT HEADLAMPS	Not Necessary	5,420.00 FN	*- FN
5	1		*FRONT GRILLE ASSY	Not Necessary	360.00 FN	*- FN
6	1		*FRONT GRILLE LOGO	Not Necessary	75.00 FN	*- FN
7	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	396.80 FN	*- FN
8	1		*FRONT BUMPER	Dented / Deformed	794.60 FN	*682.00 FN
9	2		*FRONT BUMPER FOG LAMPS	Not Necessary	720.80 FN	*- FN
10	2		*FRONT BUMPER FOG LAMP CHROME MOULDINGS	Not Necessary	156.00 FN	*- FN
11	1		*FRONT BUMPER REINFORCEMENT	Bent	395.00 FN	*280.00 FN
12	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	139.00 FN	*- FN
13	1		*FRONT BUMPER TOW HOOK COVER	Missing	16.00 FN	*16.00 FN
14	1		*REAR WINDSCREEN MOULDING	Necessary	84.05 FN	*84.05 FN
15	1		*REAR TAILGATE	Badly Dented	1,400.61 FN	*1,400.61 FN
16	1		*REAR TAILGATE LOCK	Dented / Damaged	176.40 FN	*176.40 FN
17	1		*REAR TAILGATE LOGO	Not Necessary	88.00 FN	*- FN
18	1		*REAR TAILGATE RUBBER	Twisted	121.80 FN	*121.80 FN
19	1		*REAR TAILGATE AWD EMBLEM	Necessary	72.05 FN	*72.05 FN
20	1		*REAR TAILGATE FORESTER EMBLEM	Necessary	72.05 FN	*72.05 FN
21	1		*REAR TAILGATE SUBARU EMBLEM	Necessary	42.90 FN	*42.90 FN
22	2		*REAR TAILLAMPS	Not Necessary	874.10 FN	*- FN
23	1		*REAR END PANEL	Dented	320.10 FN	*320.10 FN
24	1		*REAR END PANEL INNER GARNISH	Twisted	40.00 FN	*40.00 FN
25	1		*REAR KEYLESS SENSOR	Not Necessary	195.85 FN	*- FN
26	1		*REAR BUMPER	Deformed	700.00 FN	*680.00 FN
27	1		*REAR BUMPER BEAM	Not fitted	195.00 FN	*- FN
28	1		*REAR BUMPER INNER SPONGE	Not fitted	121.60 FN	*- FN
29	2		*REAR BUMPER REFLECTORS	Not Necessary	91.40 FN	*- FN
30	1		*REAR BUMPER REINFORCEMENT	Bent	320.00 FN	*320.00 FN
31	2		*REAR BUMPER SIDE RETAINERS	Necessary	97.20 FN	*97.20 FN
32	1		*REAR SPARE TYRE TOOLS SPONGE	Torn	320.55 FN	*320.55 FN
33	1		*REAR EXHAUST SILENCER	Not Necessary	601.20 FN	*- FN
34	2		*REAR EXHAUST MOUNTINGS	Not Necessary	57.00 FN	*- FN
35	1		*REAR EXHAUST CHROME PIPE	Not Necessary	105.50 FN	*- FN
36	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
37	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*40.00 FS
38	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
39	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
40	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	16,447.96	5,105.71
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,584.80	472.57
Total Parts (\$\$)	14,863.16	4,633.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
5	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE ,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
8	TO APPLY UNDERCOATING	New	200.00	60.00
9	PANEL BEATING	New	1,600.00	1,100.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,400.00
Gross Labour Cost (S\$)			4,170.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >