3/8/23, 4:22 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22011234/UQP3Q2

08/03/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00005302201

Claimant Vehicle

GBC9546T

Insured

SMH1251P

No: Date of Loss:

29/10/2022

Vehicle No:

Nature of Claim: TP

Claim No:

SNM22D207801/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBC9546T Reg No:

Make & Model: NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A)

Engine No: YD25342269A

Reg. Date: 20/03/2014 (Man. Year: 2013) Chassis No: Odometer:

JN1MC2E26Z0001629

164067 km

Colour: White

Engine Capacity:

2488 cc

Market Value/New Car

N/A

Sum Insured (S\$):

Price:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 Front Left Side: KAPSEN 6 mm Rear Left Side: Raxus 6 mm Front Right Side: KAPSEN 6 mm Rear Right Side: Raxus 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,129.00	3,109.64	1,019.36	24.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	2,440.00	1,080.00	30.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,649.00	5,549.64	2,099.36	27.45
+ GST 8.00/8.00% (S\$)	611.92	443.97	167.95	27.45
Nett Amount (S\$)	8,260.92	5,993.61	2,267.31	27.45

INSPECTION

Date of Assignment: 09/11/2022

Autolution Industrial Pte Ltd (Ubi)

Date Inspected: 22/11/2022 Inspected At: 19 Ubi Road 4

Singapore 408623

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/8/23, 4:22 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Mar 2023)

Parts: N/A NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBC9546T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM -BACK DOOR NV350 URVAN	Necessary	118.70 FN	*118.70 FN
2	1		*EMBLEM -REAR NISSAN	Necessary	101.90 FN	*101.90 FN
3	1		*RR END CARPET PLATE	Not Necessary	64.70 FN	*- FN
4	1		*WEATHER STRIP TAIL GATE	Twisted	145.00 FN	*145.00 FN
5	1		*GLASS -TAIL GATE	Not Necessary	961.20 FN	*- FN
6	1		*TAIL GATE	Dented	2,157.10 FN	*2,157.10 FN
7	1		*INNER BRACKET RR BUMPER	Repair	185.80 FN	*- FN
8	10		*CLIP RR BUMPER	Necessary	14.00 FN	*14.00 FN
9	1		*REAR BUMPER	Dented	720.60 FN	*720.60 FN
10	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
11	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
12	1		*SENSOR -REVERSE	Shorted	250.00 FS	*250.00 FS
13	1		*70KM/H	Necessary	15.00 FS	*15.00 FS
14	1		*OUTER RR END PANEL	Dented	158.80 FS	*158.80 FS
F=Fra	nchise	part. S=SpcN	ett. N=NettItemDisc.	_		
				Sub Total (S\$)	5,022.80	3,761.10
			- Nett Item Discount on	N Items 20.00/20.00% (S\$)	893.80	651.46
				Total Parts (S\$)	4,129.00	3,109.64
			Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PERFORM RUSTPROOFING OUTER RR END PANEL	New	120.00	120.00
2	CHARGES TO REPAIR BOTH RR FENDER & INNER RR FENDER RENEW OUTER RR END PANEL ,TAIL GATE AND REAR BUMPER	New	1,400.00	1,000.00
3	CHARGES TO SPRAY PAINTING SAME	New	1,250.00	750.00
4	RENEW REAR WINDSCREEN GLASS	New	240.00	180.00
5	APPLY SEALANT TO TAIL GATE AND OUTER RR END PANEL	New	200.00	100.00
6	REMOVE AND TRANSFER TAIL GATE MECHANISM	New	120.00	120.00
7	TO REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK REAR WIRING SYSTEM	New	80.00	60.00
8	RENEW REVERSE SENSOR	New	110.00	110.00
	Gross Labour	Cost (S\$)	3,520.00	2,440.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >