

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011235/ENP3Q2**Date:** 07/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00105932204

Claimant Vehicle No : SKE3281D **Insured Vehicle No :** GBH6955P

Date of Loss: 03/11/2022 Nature of Claim: TP Claim No: SNM22D207926/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE3281D**

Make & Model: BMW Z4, 2.0 (A) Engine No: A3670115N20B20A

Reg. Date: 24/02/2012 (Man. Year: 2011) Chassis No: WBALL32020J080122

Colour: White Odometer: 64519 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm

Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	12,294.05	8,320.67	3,973.38	32.32	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,910.00	1,730.00	1,180.00	40.55	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	15,204.05	10,050.67	5,153.38	33.89	
Approved Total (Overridden) (S\$)		8,050.00			
	(S\$)	15,204.05	8,050.00	7,154.05	47.05
	+ GST 7.00/7.00% (S\$)	1,064.28	563.50	500.78	47.05
	Nett Amount (S\$)	16,268.33	8,613.50	7,654.83	47.05

INSPECTION

Date of Assignment: 09/11/2022

Date Inspected: 09/11/2022 Inspected At: Shu Fatt Auto Works (HQ)
Block 1009 Bukit Merah Lane 3, #01-90
Singapore 159723

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Dec 2022)	
Parts:	N/A	BMW Z4 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE3281D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RT DOOR	Dented	2,176.60 F	*2,176.60 FN
2	1		*RT DOOR GLASS	Broken	482.95 F	*482.95 FN
3	1		*RT DOOR GLASS REGULATOR	Bent	489.05 F	*489.05 FN
4	1		*RT DOOR GLASS REGULATOR MOTOR	Not Necessary	338.55 F	*- FN
5	1		*RT DOOR GLASS OUTER MOULDING	Crushed	142.25 F	*142.25 FN
6	1		*RT DOOR GLASS INNER MOULDING	Crushed	289.15 F	*289.15 FN
7	1		*RT DOOR OUTER HANDLE	Not Necessary	898.55 F	*- FN
8	1		*RT WING MIRROR	Broken	871.75 F	*871.75 FN
9	1		*RT WING MIRROR COVER	Missing	185.05 F	*185.05 FN
10	1		*RT WING MIRROR GLASS	Broken	241.45 F	*241.45 FN
11	1		*RT DOOR RUBBER	Necessary	95.50 F	*95.50 FN
12	2		*RT DOOR HINGES	Not Necessary	156.10 F	*- FN
13	1		*RT DOOR INNER BOARD	Deformed	2,572.50 F	*2,572.50 FN
14	1		*RT FRT WINDSCREEN PILLAR MOULDING	Cut	425.10 F	*425.10 FN
15	1		*RT WING MIRROR INNER COVER	Not Necessary	121.55 F	*- FN
16	1		*RT WING MIRROR INNER COVER SPEAKER	Not Necessary	86.10 F	*- FN
17	1		*RT BODY RUBBER	Not Necessary	155.50 F	*- FN
18	1		*SET REAR BUMPER CLIPS	Not Necessary	60.00 F	*- FN
19	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	381.60 F	*- FN
20	1		*RT FRT FENDER EMBLEM	Necessary	110.95 F	*110.95 FN
21	1		*RT FRT FENDER S DRIVE 2.0I EMBLEM	Necessary	155.35 F	*155.35 FN
22	1		*RT REAR RIM	Not Necessary	1,337.50 F	*- FN
23	1		*RIGHT ROCKER GARNISH	Deformed	385.30 F	*385.30 FN
24	1		*RIGHT DOOR FRAME GARNISH	Distorted	135.65 F	*135.65 FN

F=Franchise part. N=NettItemDisc.

Sub Total (S\$)	12,294.05	8,758.60
- Nett Item Discount on N Items 0.00/5.00% (S\$)	0.00	437.93
Total Parts (S\$)	12,294.05	8,320.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK ,STRAIGHTEN RT FRT FENDER ,RT REAR FENDER ,RT DOOR FRT PILLAR ,RT DOOR REAR PILLAR ,RENEW RT DOOR AND ASSEMBLY	New	1,050.00	400.00
2	TO RESPRAY DAMAGED PARTS	New	1,050.00	1,000.00
3	TO REMOVE ,REPLACE RT DOOR GLASS ,REGULATOR ,MOTOR ,BOARD ,INNER LOCK ,OUTER LOCK ,MOULDINGS ,RUBBERS AND ASSEMBLY	New	250.00	100.00
4	TO REMOVE CARPETS ,UPHOLSTERY ,SEATS TO FACILITATE REPAIRS AND ASSEMBLY	New	120.00	50.00
5	TO RESEAL JOINTS ,REINSULATE ,ANTI RUST PANELS AND ASSEMBLY	New	60.00	30.00
6	TO REMOVE ,REPLACE RT REAR RIM ,TYRE AND ASSEMBLY	New	80.00	0.00
7	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	150.00	0.00
8	TO CHECK AND RESET ECU	New	150.00	150.00
			Gross Labour Cost (\$\$)	2,910.00
				1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >