

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22011238/EVP3Q2**Date:** 02/12/2022**REFERENCE**

Insured/Claimant: ANG HON HUANG Policy No: DMPCSNW00231802201

Date of Loss: 05/11/2022 Nature of Claim: OD Claim No: SNM22D207993/C01/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMF2559G**  
 Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B11031354  
 Reg. Date: 31/10/2018 (Man. Year: 2018) Chassis No: JHMGK3850JX227087  
 Colour: Blue Odometer: 65991 km  
 Engine Capacity: 1318 cc  
 Market Value/New Car Price: S\$74,000.00  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15  
 Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm  
 Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,510.00	2,410.00	100.00	3.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,323.84	1,323.84	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,833.84</b>	<b>3,733.84</b>	<b>100.00</b>	<b>2.61</b>
<b>- Excess (S\$)</b>	0.00	1,000.00	-1,000.00	
<b>(S\$)</b>	3,833.84	2,733.84	1,100.00	28.69
<b>+ GST 7.00/7.00% (S\$)</b>	268.37	191.37	77.00	28.69
<b>Nett Amount (S\$)</b>	<b>4,102.21</b>	<b>2,925.21</b>	<b>1,177.00</b>	<b>28.69</b>

**INSPECTION**

Date of Assignment: 09/11/2022 Present Location: Goldbell Engineering Pte Ltd (Tuas)  
 Date Inspected: 10/11/2022 Inspected At: Goldbell Engineering Pte Ltd (Tuas)  
 10 Tuas Ave 18  
 Singapore 638894  
 Estimated Period of Repair: 7.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$100.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2022)
Parts:	144	HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF2559G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts		2,510.00 F	*2,410.00 F
				Total Parts (S\$)	2,510.00	2,410.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Total of Labour	New	831.60	831.60
2	Total Paint Including Material	New	492.24	492.24
<b>Gross Labour Cost (S\$)</b>			<b>1,323.84</b>	<b>1,323.84</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >