

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011239/UVP3Q2**Date:** 21/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00098442200

Claimant Vehicle No : SGW8000T **Insured Vehicle No :** SLZ1870U

Date of Loss: 07/11/2022 Nature of Claim: TP Claim No: SNM22D208047/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW8000T**

Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1792852

Reg. Date: 28/06/2016 (Man. Year: 2016) Chassis No: JTDGG20W40J004539

Colour: Silver Odometer: 143769 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,829.37	4,848.35	981.02	16.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	2,950.00	610.00	17.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,389.37	7,798.35	1,591.02	16.94
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	9,389.37	7,000.00	2,389.37	25.45
+ GST 7.00/7.00% (S\$)	657.26	490.00	167.26	25.45
Nett Amount (S\$)	10,046.63	7,490.00	2,556.63	25.45

INSPECTION

Date of Assignment: 09/11/2022

Date Inspected: 11/11/2022 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE:NEW PARTS REPLACEMENT

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGW8000T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE	Badly Dented	1,400.00 FL	*1,400.00 FL
2	4		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
3	1		*REAR GATE LAMP LH	Cracked	195.00 FL	*195.00 FL
4	1		*REAR GATE INNER RUBBER	Not Necessary	320.00 FL	*- FL
5	1		*REAR GATE INNER TRIM BOARD	Torn	450.00 FL	*450.00 FL
6	8		*TRIM BOARD CLIPS	Not Necessary	48.00 FL	*- FL
7	1		*REAR BUMPER	Distorted	595.00 FL	*595.00 FL
8	2		*REAR BUMPER RETAINER LH	Cracked	190.00 FL	*190.00 FL
9	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
10	1		*REAR BUMPER BRACKET LH	Bent	65.00 FL	*65.00 FL
11	1		*REAR BUMPER REFLECTOR LH	Cracked	65.00 FL	*65.00 FL
12	1		*REAR LH TAIL LAMP	Cracked	245.00 FL	*245.00 FL
13	1		*REAR LH TAIL LAMP PANEL	Bent	75.80 FL	*75.80 FL
14	1		*REAR END PANEL	Repair	536.70 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	285.00 FL	*285.00 FL
16	6		*TOP GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
17	1		*REAR LH FENDER	Badly Dented	955.00 FL	*955.00 FL
18	1		*REAR LH FENDER AIR DUCT	Twisted	140.00 FL	*140.00 FL
19	1		*REAR LH FENDER GLASS MOULDING	Necessary	425.00 FL	*425.00 FL
20	1		*REAR LH FENDER INNER COWLING	Torn	95.00 FL	*95.00 FL
21	8		*INNER COWLING CLIPS	Necessary	40.00 FL	*40.00 FL
22	2		*REAR PETROL TANK COVER RIVETS	Necessary	10.00 FL	*10.00 FL
23	1		*REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
24	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS
25	1		*REAR LH FENDER GLASS GUM	Necessary	50.00 FS	*40.00 FS
26	1		*REAR LH FENDER INNER TRIM BOARD	Deformed / Torn	434.20 FL	*434.20 FL
27	1		*REAR SPARE TYRE TOOLS BRACKET	Bent	286.80 FL	*286.80 FL
28	1		*REAR FLOOR PANEL SIDE JOINT LH	Bent	236.00 FL	*236.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,652.50	6,437.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,823.13	1,589.45
Total Parts (\$\$)	5,829.37	4,848.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	REMOVE & REFIX REAR FENDER GLASS	New	60.00	60.00
4	REMOVE & REFIX CUSHION AND SEATS	New	180.00	100.00
5	CAVITY PROTECTION ON ALL AFFECTED AREAS	New	120.00	90.00
6	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	150.00	60.00
7	LABOUR CHARGE	New	1,500.00	1,300.00
8	SPRAY PAINTING	New	1,400.00	1,200.00
Gross Labour Cost (S\$)			3,560.00	2,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >