



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 8989M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH BUMPER GUIDE (SN)	CRACKED	163.55	163.55
1	# REAR BUMPER PANEL PRIMED (M/PMA) (SN)	SCRATCHED	1,536.45	1,536.45
30	EXPANDING RIVET BLACK @\$1.40 (SN)	NECESSARY	42.00	14.00
1	# RR RH WHEEL ARCH TRIM PRIMED (SN)	NOT NECESSARY	302.95	-
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			2,124.95	1,794.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER, RIGHT REAR WHEEL ARCH COVER AND TO KNOCK OUT RIGHT REAR FENDER.		2,550.00	1,700.00
	TO RESPRAY REAR BUMPER, RIGHT REAR FENDER AND RIGHT REAR WHEEL ARCH COVER.		2,666.00	2,533.00
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS. (1X).	NOT NECESSARY	531.00	-
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIR.		271.00	257.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00
	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	168.00
			6,372.00	4,826.00
	GRAND TOTAL		8,496.95	6,620.00
	RECOMMENDED COST OF REPAIRS			6,620.00

Report Ref No. CS/SMR22011241/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.