

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011246/KVP3Q2**Date:** 20/04/2023**REFERENCE**

Insured/Claimant:	NG SUN GIAP (HUANG SHANYE)	Policy No:	DMHCSNW00002032200
Date of Loss:	03/11/2022	Nature of Claim:	OD
		Claim No:	SNM22D207961/C01/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND7658U	Engine No:	1NZ9327040
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Chassis No:	NHP1707251043
Reg. Date:	24/01/2022 (Man. Year: 2021)	Odometer:	54080 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$113,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 2 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,540.00	4,870.00	670.00	12.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,189.24	1,105.24	84.00	7.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,729.24	5,975.24	754.00	11.20
- Excess (S\$)	0.00	1,250.00	-1,250.00	
(S\$)	6,729.24	4,725.24	2,004.00	29.78
+ GST 7.00/8.00% (S\$)	471.05	378.02	93.03	19.75
Nett Amount (S\$)	7,200.29	5,103.26	2,097.03	29.12

INSPECTION

Date of Assignment:	08/11/2022 Present Location:	Goldbell Engineering Pte Ltd (Tuas) 5035 ANG MO KIO INDUSTRIAL PARK 2, #01-367, ANG MO KIO INDUSTRIAL PARK 2, SINGAPORE 569538 Repairer: Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	09/11/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND7658U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts		3,870.00 F	*3,200.00 F
Supplementary #1						
2	1		*LH FRONT SEAT BELT	Jammed	420.00 F	*420.00 F
3	1		*RH FRONT SEAT BELT	Jammed	420.00 F	*420.00 F
Supplementary #2						
4	1		*FRONT SUBFRAME	Bent	830.00 F	*830.00 F
F=Franchise part.						
Total Parts (S\$)					5,540.00	4,870.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total of Labour	New	588.00	504.00
2	Total Paint Including Material	New	601.24	601.24
Gross Labour Cost (S\$)			1,189.24	1,105.24

Report was unsubmitted during this print-out.

< END OF ESTIMATES >