



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22011247/Tqy3m4 Date: 01/03/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 2548T	Veh. Inspected	YN 7296Y
	Policy No.	D-22098760MFVS/2	Coverage (\$)	0.00
	Claim No.	D22003494MFVS	Excess (\$)	0.00
	Assign From	JOANNE TAN JO ANN	Assign Date	09/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FEB21	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	FEB21CA00059	Colour	YELLOW
	Odometer	405427 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	6/6 mm
	L/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/11/2022	Inspection Date	10/11/2022
	Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	