

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI22011251/GVY3E2**Date:** 03/01/2023**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMPG22003394
<b>Claimant Vehicle No :</b>	SHC4738T	<b>Insured Vehicle No :</b>	SMV9284T
Date of Loss:	08/11/2022	Nature of Claim:	TP
		Claim No:	CDMPG22002402

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC4738T</b>		
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Engine No:	2ZR6265060
Reg. Date:	20/01/2015 (Man. Year: 2014)	Chassis No:	JTDKN36U605755856
Colour:	Maroon	Odometer:	774288 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,935.70	29.40	2,906.30	99.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,112.00	800.00	1,312.00	62.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,047.70</b>	<b>829.40</b>	<b>4,218.30</b>	<b>83.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>200.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,047.70</b>	<b>200.00</b>	<b>4,847.70</b>	<b>96.04</b>

**INSPECTION**

Date of Assignment:	09/11/2022	
Date Inspected:	11/11/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC4738T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STRIDES LOGO (SN)	Necessary	7.80 F	*7.80 F
2	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
3	10		*BUMPER CLIPS	Not Necessary	24.00 F	*- F
4	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
5	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	108.70 F	*- F
6	1		*BUMPER SEAL, RR LH	Not Necessary	101.80 F	*- F
7	1		*BUMPER LIP COVER RR/LH	Not Necessary	93.90 F	*- F
8	1		*FENDER LINER R/LH	Not Necessary	159.80 F	*- F
9	1		*TAIL LAMP BRACKET, LH	Not Necessary	35.20 F	*- F
10	1		*TAIL LAMP LH	Not Necessary	618.60 F	*- F
11	1		*LID ASSY, FUEL	Not Necessary	116.80 F	*- F
12	1		*STICKER DECAL PETROL ONLY	Not Necessary	7.80 F	*- F
13	1		*BUMPER REAR	Repair	478.90 F	*- F
14	1		*FENDER RR/LH	Repair	980.80 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>2,935.70</b>	<b>29.40</b>
--------------------------	-----------------	--------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	936.00	400.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,112.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >