



Case Details

Case Reference Number : TAX/11/22/2013
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4738T

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19797-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : ERGO Insurance Pte Ltd
 Accident Date and Time : 08/11/2022 09:30 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
Standard	Main			BUMPER REAR	1	478.90	478.90	25.00	359.17	Replace	1	0.00	Repair	✓	X Repair
Standard	Main			BUMPER CLIPS (10 PCS)	10	2.40	24.00	25.00	18.00	Replace	0	0.00	Not Give	✓	X
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0.00	Not Give	✓	X
Standard	Main			BUMPER SIDE RETAINER RR/LH	1	108.70	108.70	25.00	81.53	Replace	0	0.00	Not Give	✓	X
Standard	Main			BUMPER SEAL, RR LH	1	101.80	101.80	25.00	76.35	Replace	0	0.00	Not Give	✓	X
Standard	Main			BUMPER LIP COVER RR/LH	1	93.90	93.90	25.00	70.43	Replace	0	0.00	Not Give	✓	X
Standard	Main			FENDER RR/LH	1	980.80	980.80	25.00	735.60	Replace	1	0.00	Repair	✓	X Repair
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓	-
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓	-
Standard	Main			FENDER LINER R/LH	1	159.80	159.80	25.00	119.85	Replace	0	0.00	Not Give	✓	X
Standard	Main			TAIL LAMP BRACKET, LH	1	35.20	35.20	25.00	26.40	Replace	0	0.00	Not Give	✓	X
Standard	Main			TAIL LAMP LH	1	618.60	618.60	10.00	556.74	Replace	0	0.00	Not Give	✓	X
Standard	Main			LID ASSY, FUEL	1	116.80	116.80	25.00	87.60	Replace	0	0.00	Not Give	✓	X
Standard	Main			STICKER PETROL ONLY	1	7.80	7.80	0.00	7.80	Replace	0	0.00	Not Give	✓	X
									Total Spare Part Cost	2,348.87				Surveyor Total	29.40
									Lump Sum Discount (%)	20.00				Lump Sum Dis (%)	20.00
									Final Spare Part Cost	1,879.10				Final Sur Total	23.52

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH REAR PORTION	676.00	400.00	
Total:			676.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	178.00	200.00	
2	Main	TO RESPRAY REAR FENDER LH	378.00	200.00	
3	Main	TO RESPRAY FUEL LID COVER	180.00	0.00	X <i>na</i>
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0.00	X
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0.00	X
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00	X
4	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	X
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00	X
Total:			500.00	0.00	<i>na</i>

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,879.10	23.52
Total Labour Cost	676.00	400.00
Total Spray Painting	936.00	400.00
Other	500.00	0.00
Overall Total	3,991.10	823.52
Lump Sum Repair Option		☒
Lump Sum Total	4,000.00	800.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Surveyor Approved Amount		800.00
No of Repair Days*	5	4
Remarks	.	REQ NBV / LUMP SUM REPAIR AFTER PAINT PHOTOS. FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SHIWEI/2022 11/11/22 5:15 PM
Surveyor Name		GuoQiang
Signature		
Survey Date	11/11/2022	

LKK Auto Consultants hence **notify**
the **Repairer** of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental repairs must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: