

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS22011253/UQY3Q2**Date:** 16/11/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2003024562
<b>Claimant Vehicle No :</b>	SMJ7137L	<b>Insured Vehicle No :</b>	GBJ1378C
Date of Loss:	07/11/2022	Nature of Claim:	TP
		Claim No:	2022 22007990KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMJ7137L</b>		
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Engine No:	2ZR0C83411
Reg. Date:	18/03/2019 (Man. Year: 2018)	Chassis No:	JTDZS3EU20J036278
Colour:	Silver	Odometer:	23821 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,139.55	3,623.80	2,515.75	40.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	920.00	780.00	45.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,839.55</b>	<b>4,543.80</b>	<b>3,295.75</b>	<b>42.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,839.55</b>	<b>3,600.00</b>	<b>4,239.55</b>	<b>54.08</b>

INSPECTION

Date of Assignment:	09/11/2022	
Date Inspected:	10/11/2022	Inspected At: T K Lee Automotive Pte Ltd (HQ) NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2022)
<b>Parts:</b>	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ7137L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	786.45 FL	*786.45 FL
2	1		*FRONT BUMPER LOGO	Scratched	128.63 FL	*128.63 FL
3	1		*FRONT BUMPER LOWER GARNISH	Dented	563.19 FL	*563.19 FL
4	1		*FRONT BUMPER GRILLE -TOP	Cracked	374.45 FL	*374.45 FL
5	1		*FRONT BUMPER SPONGE	Torn	180.92 FL	*180.92 FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	551.60 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINERS -R/L	Not Necessary	173.90 FL	*- FL
8	1		*FRONT BONNET	Repair	914.10 FL	*- FL
9	1		*FRONT BONNET LOCK	Not Necessary	180.63 FL	*- FL
10	1		*FRONT BONNET SEAL	Not Necessary	86.10 FL	*- FL
11	1		*FRONT BONNET INSULATOR	Not Necessary	281.60 FL	*- FL
12	1		*FRONT HEADLAMP -LH	Cracked	2,826.23 FL	*2,678.10 FL
13	1		*FRONT SUPPORT PANEL	Repair	991.60 FL	*- FL
14	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
15	1		*FRONT NUMBER PLATE	Bent	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,149.40</b>	<b>4,801.74</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,009.85	1,177.94
<b>Total Parts (\$\$)</b>	<b>6,139.55</b>	<b>3,623.80</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
2	TO TUFF KOTE	New	50.00	0.00
3	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS	New	800.00	400.00
4	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS	New	800.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,700.00</b>	<b>920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >