

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011259/UPA3Q2**Date:** 17/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210055199-01
Claimant Vehicle No :	SLE1948R	Insured Vehicle No :	SLN2455S
Date of Loss:	06/11/2022	Nature of Claim:	TP
		Claim No:	6764991353SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE1948R		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Engine No:	1ZR586840
Reg. Date:	13/07/2016 (Man. Year: 2016)	Chassis No:	MR053REH104554832
Colour:	Silver	Odometer:	569577 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55Z R16	Rear Tyre Size:	205/55Z R16
Front Left Side:	Farroad 6 mm	Rear Left Side:	Farroad 6 mm
Front Right Side:	Farroad 6 mm	Rear Right Side:	Farroad 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,069.40	3,910.75	6,158.65	61.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	2,120.00	1,730.00	44.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,919.40	6,030.75	7,888.65	56.67
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	13,919.40	4,800.00	9,119.40	65.52
+ GST 7.00/7.00% (\$\$)	974.36	336.00	638.36	65.52
Nett Amount (\$\$)	14,893.76	5,136.00	9,757.76	65.52
+ Car Rental (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,438.00		
Global Sum Settlement (\$\$)		5,430.00		

INSPECTION

Date of Assignment:	15/11/2022	
Date Inspected:	15/11/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,266.10 F	*- FL
2	1		*BOOTLID REAR LOGO	Necessary	68.50 F	*68.50 FL
3	1		*BOOTLID COROLLA EMBLEM	Necessary	62.80 F	*62.80 FL
4	1		*BOOTLID ALTIS EMBLEM	Necessary	58.00 F	*58.00 FL
5	1		*BOOTLID INNER LOCK	Twisted	409.10 F	*409.10 FL
6	1		*BOOTLID LOCK STRICKER	Not Necessary	66.80 F	*- FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	282.30 F	*282.30 FL
8	2		*BOOTLID REFLECTORS	Not Necessary	901.80 F	*- FL
9	1		*BOOTLID INNER TRIM	Not Necessary	366.10 F	*- FL
10	1		*REAR BUMPER	Dented / Deformed	755.10 F	*684.10 FL
11	1		*REAR BUMPER BEAM	Dented	505.40 F	*408.20 FL
12	2		*REAR BUMPER REFLECTORS	Cracked	120.00 F	*120.00 FL
13	2		*REAR BUMPER SIDE RETAINERS	Bent	130.00 F	*130.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR END PANEL	Dented	788.20 F	*615.00 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	362.30 F	*288.00 FL
17	2		*TAILLAMPS	Cracked	1,160.00 F	*1,160.00 FL
18	2		*TAILLAMP LOWER BRACKETS	Cracked	130.00 F	*130.00 FL
19	1		*REAR ANTENNA SENSOR	Not Necessary	241.20 F	*- FL
20	1		*REAR FLOOR PANEL	Repair	1,145.20 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Torn	620.50 F	*415.00 FL
22	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
23	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
24	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,069.40	5,131.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,220.25
Total Parts (S\$)	10,069.40	3,910.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	60.00
5	TO SPRAY RUST PROOFING	New	100.00	40.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,600.00	850.00
7	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
Gross Labour Cost (S\$)			3,850.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >