7/4/23, 11:03 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22011261/UQY3M4

04/07/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00069012201

Claimant Vehicle

SLZ2985R

Insured

YQ2439U

No:

Vehicle No:

Date of Loss:

30/10/2022

Nature of Claim: TP

Claim No:

SNM22D208021/C02/LEEPG

Yes

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLZ2985R Reg No:

Make & Model: TOYOTA ALLION, 1.5 (A) Engine No: 1NZD239912 Reg. Date: 13/01/2009 (Man. Year: 2008) Chassis No: NZT2603034711 Colour: White Odometer: 257347 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Engine Modification: Pre-accident Condition: Handbrake (Serviceable): Yes No

CONDITION OF TYRES

Front Tyre Size: 185/70R14 Rear Tyre Size: 185/70R14 Rear Left Side: Front Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,229.27	2,250.55	3,978.72	63.87
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,830.00	1,500.00	2,330.00	60.84
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calcul	ated Gross Total (S\$)	10,059.27	3,750.55	6,308.72	62.72
Approved To	otal (Overridden) (S\$)		3,000.00		
	(S\$)	10,059.27	3,000.00	7,059.27	70.18
+	GST 8.00/8.00% (S\$)	804.74	240.00	564.74	70.18
	Nett Amount (S\$)	10,864.01	3,240.00	7,624.01	70.18

INSPECTION

Date of Assignment: 09/11/2022

Yew Tee Automobile Tech Pte Ltd (Woodlands)

39 Woodlands Close #01-12, Mega@Woodlands Date Inspected: 14/11/2022 Inspected At:

Singapore 737856

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS. (REPAIR COST NOT CONCLUDE)

7/4/23, 11:03 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jul 2023)

Parts: 143 TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ2985R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE HOLDER	Serviceable	150.00 FL	*- FL
2	2		*REAR NUMBER PLATE LAMP	Not Necessary	220.00 FL	*- FL
3	1		*REAR BUMPER	Dented/Deformed	850.20 FL	*850.20 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Bent	95.40 FL	*95.40 FL
5	1		*REAR BUMPER SIDE RETAINER RH	Bent	95.40 FL	*95.40 FL
6	1		*REAR BUMPER BRACKET LH	Not Necessary	93.00 FL	*- FL
7	1		*REAR BUMPER BRACKET RH	Not Necessary	93.00 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	No such part	525.80 FL	*- FL
9	1		*REAR BUMPER REFLECTOR LH	Not Necessary	98.20 FL	*- FL
10	1		*REAR BUMPER REFLECTOR RH	Not Necessary	98.20 FL	*- FL
11	1		*REAR BUMPER STAY LH	Not Necessary	106.80 FL	*- FL
12	1		*REAR BUMPER STAY RH	Not Necessary	106.80 FL	*- FL
13	1		*BOOT LID	Dented	823.10 FL	*823.10 FL
14	1		*BOOT LID HINGES LH	Not Necessary	152.30 FL	*- FL
15	1		*BOOT LID HINGES RH	Not Necessary	152.30 FL	*- FL
16	1		*BOOT LID RUBBER	Serviceable	184.70 FL	*- FL
17	1		*BOOT LID LOCK	Twisted	220.50 FL	*220.50 FL
18	1		*BOOT LID LOCK CATCH	Not Necessary	85.00 FL	*- FL
19	1		*BOOT LID LOGO	Necessary	56.60 FL	*56.60 FL
20	1		*BOOT LID ALLION EMBLEM	Necessary	55.00 FL	*55.00 FL
21	1		*BOOT LID A15 EMBLEM	Necessary	53.00 FL	*53.00 FL
22	1		*BOOT LID OUTER CHROME GARNISH	Cracked	378.20 FL	*378.20 FL
23	1		*REAR END PANEL	Repair	274.40 FL	*- FL
24	1		*REAR END PANEL TOP GARNISH	Not Necessary	309.50 FL	*- FL
25	1		*REAR TAILLAMP LH	Serviceable	373.00 FL	*- FL
26	1		*REAR TAILLAMP RH	Serviceable	373.00 FL	*- FL
27	1		*REAR TAILLAMP LOWER PANEL LH	Repair	362.50 FL	*- FL
28	1		*REAR TAILLAMP LOWER PANEL RH	Repair	362.50 FL	*- FL
29	1		*REAR SPARE TYRE COMPARTMENT	Repair	1,097.30 FL	*- FL
30	1		*REAR NUMBER PLATE	Scratched	45.00 FS	*40.00 FS
31	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
32	1		*SET REAR BUMPER SENSORS	Shorted	260.00 FS	*200.00 FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	8,190.70	2,907.40
	- List Item Discount on L Items 25.00/25.00% (S\$)			1,961.43	656.85	

Sub Total (S\$)	8,190.70	2,907.40
List Item Discount on L Items 25.00/25.00% (S\$)	1,961.43	656.85
· · · · · · · · · · · · · · · · · · ·	r	

Total Parts (S\$) 6,229.27 2,250.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	50.00	20.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	50.00
3	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	100.00	80.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,800.00	520.00
5	TO CARRY-OUT BODY CAVITY PRESERVATION	New	60.00	30.00
6	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	80.00	0.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	60.00	0.00
8	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,600.00	800.00
	Gross Labou	ır Cost (S\$)	3,830.00	1,500.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >