

ASS. REC. BY: Marcus

REF:

CS/CT122011261/4943ASSIGNMENT

From: *

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SL22985R

at Workshop m/s

Yew Tee Mega 3pm

Insured:

Y224394

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$12k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

4142A

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL22985R

Yr Regn:

13/01/09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /

Make:

Toyota A110A

c.c

1496

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

257347

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

N2T 260 3034711Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/10/22

D.O.I.

14/11/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 10k.

28/6/23 COE used 12-01-2024 LTA \$3024
submit 4/5 \$3000 vehicle hasn't send in for repair
(Paid \$7059.27, 70%)

Date/Time, File Pass to?



Preli. Report

1)

30/6/2023

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS SI

Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
 Singapore 737856
 Tel: Fax: Email:

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5107048121-03	Date of Loss:	30/10/2022
Vehicle Reg. No.:	SLZ2985R	Driveable?	no
Driver Age:	07/05/2023	Third Party Vehicle No.:	YQ2439U
Any Injuries?	no	Contact No:	
Insured/Claimant:	TAN JUN HONG	Driver:	TAN JUN HONG

PARTS MODEL

Make/Model:	Toyota, Allion 1.5A - NZT2603	Vehicle Reg. Date:	13/01/2009
Vehicle Colour:		Engine Number:	
Chassis No:	NZT2603034711	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss Collision - Head to Rear
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	5,884.28
Miscellaneous Items	345.00
Labour	2,030.00
Paintwork Labour	1,800.00
Towing	0.00
Gross Total(S\$):	10,059.27
GST 7.00%(S\$):	704.15
Nett Amount(S\$):	10,763.42

This claim is handled by: Sky Toh T C

*not authorized
 in
 14/11/22
 1/553000/
 telephone up
 90096608*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE HOLDER <i>SVC</i>	150.00	-25.00	112.50 <i>X</i>
2	2	REAR NUMBER PLATE LAMP <i>11</i>	220.00	-25.00	165.00 <i>X</i>
3	1	REAR BUMPER <i>10/20</i>	850.20	-25.00	637.65 <i>—</i>
4	1	REAR BUMPER SIDE RETAINER LH <i>601</i>	95.40	-25.00	71.55 <i>—</i>
5	1	REAR BUMPER SIDE RETAINER RH <i>501</i>	95.40	-25.00	71.55 <i>—</i>
6	1	REAR BUMPER BRACKET LH <i>11</i>	93.00	-25.00	69.75 <i>X</i>
7	1	REAR BUMPER BRACKET RH <i>11</i>	93.00	-25.00	69.75 <i>X</i>
8	1	REAR BUMPER REINFORCEMENT <i>11</i>	525.80	-25.00	394.35 <i>X</i>
9	1	REAR BUMPER REFLECTOR LH <i>11</i>	98.20	-25.00	73.65 <i>X</i>
10	1	REAR BUMPER REFLECTOR RH <i>11</i>	98.20	-25.00	73.65 <i>X</i>
11	1	REAR BUMPER STAY LH <i>11</i>	106.80	-25.00	80.10 <i>X</i>
12	1	REAR BUMPER STAY RH <i>11</i>	106.80	-25.00	80.10 <i>X</i>
13	1	BOOT LID <i>11</i>	823.10	-25.00	617.33 <i>—</i>
14	1	BOOT LID HINGES LH <i>11</i>	152.30	-25.00	114.23 <i>X</i>
15	1	BOOT LID HINGES RH <i>11</i>	152.30	-25.00	114.23 <i>X</i>
16	1	BOOT LID RUBBER <i>SVC</i>	184.70	-25.00	138.53 <i>X</i>
17	1	BOOT LID LOCK <i>11</i>	220.50	-25.00	165.38 <i>—</i>
18	1	BOOT LID LOCK CATCH <i>11</i>	85.00	-25.00	63.75 <i>X</i>
19	1	BOOT LID LOGO <i>11</i>	56.60	-25.00	42.45 <i>—</i>
20	1	BOOT LID ALLION EMBLEM <i>11</i>	55.00	-25.00	41.25 <i>—</i>
21	1	BOOT LID A15 EMBLEM <i>11</i>	53.00	-25.00	39.75 <i>—</i>
22	1	BOOT LID OUTER CHROME GARNISH <i>11</i>	378.20	-25.00	283.65 <i>—</i>
23	1	REAR END PANEL <i>11</i>	274.40	-25.00	205.80 <i>X</i>
24	1	REAR END PANEL TOP GARNISH <i>11</i>	309.50	-25.00	232.13 <i>X</i>
25	1	REAR TAILLAMP LH <i>SVC</i>	373.00	-25.00	279.75 <i>X</i>
26	1	REAR TAILLAMP RH <i>SVC</i>	373.00	-25.00	279.75 <i>X</i>
27	1	REAR TAILLAMP LOWER PANEL LH <i>11</i>	362.50	-25.00	271.88 <i>X</i>
28	1	REAR TAILLAMP LOWER PANEL RH <i>11</i>	362.50	-25.00	271.88 <i>X</i>
29	1	REAR SPARE TYRE COMPARTMENT <i>11</i>	1,097.30	-25.00	822.98 <i>X</i>
Total Parts (S\$)					5,884.28

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE <i>SVC</i>	45.00	0.00	45.00 <i>40</i>
2	1	REAR BUMPER CLIPS (1 SET) <i>11</i>	40.00	0.00	40.00 <i>40</i>
3	1	REAR BUMPER SENSORS (1 SET) <i>11</i>	260.00	0.00	260.00 <i>200</i>
Sub Total (S\$)					345.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	0.00	50.00 <i>20</i>
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>50</i>
3	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 <i>80</i>
4	1	To Remove and Replace the above Damaged	1,800.00	0.00	1,800.00 <i>520</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
		Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.			

Gross Labour Cost (\$\$) 2,030.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	0.00	60.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	80.00	0.00	80.00
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	0.00	60.00
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,600.00	0.00	1,600.00

Gross Labour Cost (\$\$) 1,800.00

< END OF ESTIMATES >

P. 2627.4
252
1970.55
260