

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS22011263/GWY3M4**Date:** 23/12/2022**REFERENCE**

Insured/Claimant: CHEW OEI PHENG Policy No: SP2000612515-01
Date of Loss: 08/11/2022 Nature of Claim: OD Claim No: 202222007973

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW4284X**
Make & Model: AUDI A1, 1.4 TFSI S-TRONIC (185HP) (A) Engine No: CAV295621
Reg. Date: 25/05/2011 (Man. Year: 2011) Chassis No: WAUZZZ8X1BB085339
Colour: Red Odometer: 107134 km
Engine Capacity: 1390 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/35R18 Rear Tyre Size: 225/35R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,622.50	8,750.50	3,872.00	30.68
Miscellaneous Items	750.00	200.00	550.00	73.33
Labour	3,160.00	1,750.00	1,410.00	44.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,532.50	10,700.50	5,832.00	35.28
- Excess (\$\$)	0.00	3,100.00	-3,100.00	
(\$\$)	16,532.50	7,600.50	8,932.00	54.03
+ GST 7.00/7.00% (\$\$)	1,157.28	532.04	625.24	54.03
Nett Amount (\$\$)	17,689.78	8,132.54	9,557.24	54.03

INSPECTION

Date of Assignment: 09/11/2022 Present Location: Ding Auto Pte Ltd (HQ)
Date Inspected: 11/11/2022 Inspected At: Ding Auto Pte Ltd (HQ)
176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts:	144	AUDI A1 1.4 TFSI S-TRONIC (185HP) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW4284X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Deformed	680.00 F	*1,200.00 F
2	1		*FRONT BUMPER RETAINER RH (WCP)	Deformed	65.00 F	*65.00 F
3	1		*FRONT BUMPER RETAINER LH (WCP)	Deformed	65.00 F	*65.00 F
4	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	380.00 F	*380.00 F
5	1		*FRONT BUMPER REINFORCEMENT ARM RH (WCP)	Not Necessary	100.00 F	*- F
6	1		*FRONT BUMPER REINFORCEMENT ARM LH (WCP)	Not Necessary	100.00 F	*- F
7	1		*FRONT BUMPER FOAM (WCP)	Not Necessary	90.00 F	*- F
8	1		*FRONT BUMPER SIDE COVER RH (WCP)	Not Necessary	140.00 F	*- F
9	1		*FRONT BUMPER SIDE COVER LH (WCP)	Not Necessary	140.00 F	*- F
10	1		*FRONT BUMPER LOWER LIP GARNISH (WCP)	Not Necessary	220.00 F	*- F
11	1		*BONNET (WCP)	Buckled	1,450.00 F	*1,400.00 F
12	1		*BONNET HINGE RH (WCP)	Not Necessary	85.00 F	*- F
13	1		*BONNET HINGE LH (WCP)	Not Necessary	85.00 F	*- F
14	1		*BONNET LOCK (WCP)	Bent	150.00 F	*50.00 F
15	1		*BONNET DAMPER RH (WCP)	Not Necessary	85.00 F	*- F
16	1		*BONNET DAMPER LH (WCP)	Not Necessary	85.00 F	*- F
17	1		*BONNET INSULATION (WCP)	Not Necessary	140.00 F	*- F
18	1		*FRONT SUPPORT PANEL (WCP)	Broken	680.00 F	*650.00 F
19	1		*FRONT CENTRE GRILLE (WCP)	Cracked	750.00 F	*680.00 F
20	1		*GRILLE BADGE (WCP)	Not Necessary	120.00 F	*- F
21	1		*FRONT LOWER GRILLE (WCP)	Not Necessary	120.00 F	*- F
22	1		*FRONT FENDER RH (WCP)	Repair	480.00 F	*- F
23	1		*FRONT FENDER INNER COVER RH (WCP)	Not Necessary	140.00 F	*- F
24	1		*RADIATOR ASSY (WCP)	Not Necessary	480.00 F	*- F
25	1		*RADIATOR AIR GUIDE RH (WCP)	Deformed	60.00 F	*45.00 F
26	1		*RADIATOR AIR GUIDE LH (WCP)	Deformed	60.00 F	*45.00 F
27	1		*CONDENSOR ASSY (WCP)	Cut	550.00 F	*200.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*INTERCOOLER ASSY (WCP)	Bent	450.00 F	*350.00 F
29	1		*HEADLAMP ASSY RH (WCP)	Cut	1,350.00 F	*1,200.00 F
30	1		*HEADLAMP ASSY LH (WCP)	Cut	1,350.00 F	*1,200.00 F
31	1		*HEADLAMP BRACKET RH (WCP)	Not Necessary	140.00 F	*- F
32	1		*HEADLAMP BRACKET LH (WCP)	Not Necessary	140.00 F	*- F
33	1		*FOG LAMP ASSY RH (WCP)	Not Necessary	120.00 F	*- F
Supplementary #1						
34	1		*BONNET CATCH RH (WCP)	Bent	40.00 F	*40.00 F
35	1		*BONNET CATCH LH (WCP)	Bent	40.00 F	*40.00 F
36	1		*TOP CARRIER LOCK RH (WCP)	Bent	140.00 F	*140.00 F
37	1		*TOP CARRIER LOCK LH (WCP)	Bent	140.00 F	*140.00 F
38	1		*BONNET CATCH HOOK (WCP)	Missing	45.00 F	*45.00 F
39	1		*FRONT CAR PLATE (WCP)	Bent	20.00 F	*20.00 F

F=Franchise part.

Sub Total (\$\$)					11,475.00	7,955.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					1,147.50	795.50
Total Parts (\$\$)					12,622.50	8,750.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER, INNER COVER & GARNISH PANEL CLIPS (Necessary)	200.00	200.00
2	1	HEADLAMP ECU - REPROGRAMMING/RESETTING (Not Necessary)	550.00	0.00
Sub Total (\$\$)			750.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR, PANEL BEAT, STRAIGHTEN & ALIGN - ACCIDENT AREA	New	1,200.00	400.00
2	SPRAY PAINT - FRONT BUMPER, BONNET, FRONT DOOR X2, FRONT FENDER X2 & SUPPORT PANEL	New	1,500.00	1,200.00
3	REMOVE & REFIT - FRONT BUMPER COMPONENTS	New	150.00	0.00
4	ALIGN HEADLAMP/FOG LAMP & TEST WIRING	New	150.00	30.00
5	REFILL - RADIATOR COOLANT	New	80.00	60.00
6	REFILL - AIR COND GAS	New	80.00	60.00
Gross Labour Cost (\$\$)			3,160.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >