

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2000612515-01	Date of Loss:	08/11/2022
Vehicle Reg. No.:	SMW4284X	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEW OEI PHENG	Contact No:	+6596429747
Driver:	SEAN PANG		
Make/Model:	AUDI A1, 1.4 TFSI S-TRONIC (185BHP) (A)	Vehicle Reg. Date:	25/05/2011
Vehicle Colour:	Red		
Engine No:	CAV295621	Chassis No:	WAUZZZ8X1BB08533
Odometer:	107134 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Present Location:	DING AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	12,155.00
Miscellaneous Items	750.00
Labour	3,160.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	16,065.00
+ GST 7.00% (S\$)	1,124.55
Nett Amount (S\$)	17,189.55

This claim is handled by: **HENRY LEE YOON SANG**Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Nov 2022)

Parts: 144 AUDI A1 1.4 TFSI S-TRONIC (185BHP) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SMW4284X/09/11/2022 15:49

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*680.00 F
2	1		*FRONT BUMPER RETAINER RH	0.00	0.00	*65.00 F
3	1		*FRONT BUMPER RETAINER LH	0.00	0.00	*65.00 F
4	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*380.00 F
5	1		*FRONT BUMPER REINFORCEMENT ARM RH	0.00	0.00	*100.00 F
6	1		*FRONT BUMPER REINFORCEMENT ARM LH	0.00	0.00	*100.00 F
7	1		*FRONT BUMPER FOAM	0.00	0.00	*90.00 F
8	1		*FRONT BUMPER SIDE COVER RH	0.00	0.00	*140.00 F
9	1		*FRONT BUMPER SIDE COVER LH	0.00	0.00	*140.00 F
10	1		*FRONT BUMPER LOWER LIP GARNISH	0.00	0.00	*220.00 F
11	1		*BONNET	0.00	0.00	*1,450.00 F
12	1		*BONNET HINGE RH	0.00	0.00	*85.00 F
13	1		*BONNET HINGE LH	0.00	0.00	*85.00 F
14	1		*BONNET LOCK	0.00	0.00	*150.00 F
15	1		*BONNET DAMPER RH	0.00	0.00	*85.00 F
16	1		*BONNET DAMPER LH	0.00	0.00	*85.00 F
17	1		*BONNET INSULATION	0.00	0.00	*140.00 F
18	1		*FRONT SUPPORT PANEL	0.00	0.00	*680.00 F
19	1		*FRONT CENTRE GRILLE	0.00	0.00	*750.00 F
20	1		*GRILLE BADGE	0.00	0.00	*120.00 F
21	1		*FRONT LOWER GRILLE	0.00	0.00	*120.00 F
22	1		*FRONT FENDER RH	0.00	0.00	*480.00 F
23	1		*FRONT FENDER INNER COVER RH	0.00	0.00	*140.00 F
24	1		*RADIATOR ASSY	0.00	0.00	*480.00 F
25	1		*RADIATOR AIR GUIDE RH	0.00	0.00	*60.00 F
26	1		*RADIATOR AIR GUIDE LH	0.00	0.00	*60.00 F
27	1		*CONDENSOR ASSY	0.00	0.00	*550.00 F
28	1		*INTERCOOLER ASSY	0.00	0.00	*450.00 F
29	1		*HEADLAMP ASSY RH	0.00	0.00	*1,350.00 F
30	1		*HEADLAMP ASSY LH	0.00	0.00	*1,350.00 F
31	1		*HEADLAMP BRACKET RH	0.00	0.00	*140.00 F
32	1		*HEADLAMP BRACKET LH	0.00	0.00	*140.00 F
33	1		*FOG LAMP ASSY RH	0.00	0.00	*120.00 F

F=Franchise part.

Sub Total (\$\$)	11,050.00
+ Margin on L,N Items 10.00% (\$\$)	1,105.00
Total Parts (\$\$)	12,155.00

Ding Auto Pte Ltd/SMW4284X/09/11/2022 15:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT BUMPER, INNER COVER & GARNISH PANEL CLIPS	200.00
2	1	HEADLAMP ECU - REPROGRAMMING/RESETTING	550.00
Sub Total (S\$)			750.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REPAIR, PANEL BEAT, STRAIGHTEN & ALIGN - ACCIDENT AREA	New	1,200.00
2	SPRAY PAINT - FRONT BUMPER, BONNET, FRONT DOOR X2, FRONT FENDER X2 & SUPPORT PANEL	New	1,500.00
3	REMOVE & REFIT - FRONT BUMPER COMPONENTS	New	150.00
4	ALIGN HEADLAMP/FOG LAMP & TEST WIRING	New	150.00
5	REFILL - RADIATOR COOLANT	New	80.00
6	REFILL - AIR COND GAS	New	80.00
Gross Labour Cost (S\$)			3,160.00

Ding Auto Pte Ltd/SMW4284X/09/11/2022 15:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >