

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011266/UQY3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00093392203
Claimant Vehicle No :	SMM9297D	Insured Vehicle No :	YN8477K
Date of Loss:	07/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208062/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM9297D	Engine No:	PE21259582
Make & Model:	MAZDA 6, 2.0 SEDAN (A)	Chassis No:	JM6GL1072K0312486
Reg. Date:	19/07/2019 (Man. Year: 2018)	Odometer:	87304 km
Colour:	Brown		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,257.96	2,512.56	8,745.40	77.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	910.00	250.00	21.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,417.96	3,422.56	8,995.40	72.44
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	12,417.96	2,700.00	9,717.96	78.26
+ GST 8.00/8.00% (S\$)	993.44	216.00	777.44	78.26
Nett Amount (S\$)	13,411.40	2,916.00	10,495.40	78.26

INSPECTION

Date of Assignment:	10/11/2022	
Date Inspected:	05/01/2023	Inspected At: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2023)
Parts:	143	MAZDA 6 2.0 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM9297D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	1,211.00 FL	*1,211.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	59.00 FL	*59.00 FL
3	2		*FRONT BUMPER SIDE HOLDER -LH/RH	Not Necessary	58.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	579.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT GUIDE GARNISH	Not Necessary	128.00 FL	*- FL
6	1		*FRONT BUMPER FOAM	Not Necessary	82.00 FL	*- FL
7	2		*FRONT BUMPER CENTER LOWER GRILLE SIDE COVER - LH/RH	Not Necessary	124.00 FL	*- FL
8	1		*FRONT BUMPER SIDE GARNISH (CHROME) -LH/RH	N/S Cracked	76.00 FL	*38.00 FL
9	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	76.00 FL	*- FL
10	1		*FRONT BUMPER TOP COVER	Distorted	470.00 FL	*470.00 FL
11	1		*FRONT BUMPER TOP COVER INNER GARNISH	Warped	98.00 FL	*98.00 FL
12	4		*FRONT BUMPER TOP COVER INNER GARNISH TOP RIVET CLIPS	Not Necessary	23.60 FL	*- FL
13	3		*FRONT BUMPER TOP COVER INNER GARNISH SMALL CLIPS	Necessary	14.40 FL	*14.40 FL
14	3		*FRONT BUMPER TOP COVER INNER GARNISH NORMAL CLIPS	Not Necessary	13.50 FL	*- FL
15	2		*FRONT BUMPER INNER BRACKET -LH/RH	Not Necessary	75.60 FL	*- FL
16	2		*FRONT BUMPER INNER BRACKET PIN -LH/RH	Not Necessary	11.80 FL	*- FL
17	2		*HEADLAMP -LH/RH	Not Necessary	9,500.00 FL	*- FL
18	2		*HEADLAMP LOWER RETAINER-LH/RH	Not Necessary	118.00 FL	*- FL
19	1		*GRILLE BASE	Cracked	133.00 FL	*133.00 FL
20	1		*GRILLE OUTER GARNISH	Cracked	417.30 FL	*417.30 FL
21	2		*GRILLE INNER TOP BRACKET -LH/RH	Not Necessary	98.00 FL	*- FL
22	2		*GRILLE OUTER CHROME MOULDING -LH/RH	Cracked	502.00 FL	*502.00 FL
23	1		*GRILLE EMBLEM BASE	Cracked	96.00 FL	*96.00 FL
24	1		*GRILLE EMBLEM	Cracked	52.00 FL	*52.00 FL
25	1		*FRONT NUMBER PLATE WITH CASING	Bent	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 14,061.20 3,130.70

- List Item Discount on L Items 20.00/20.00% (\$\$)	2,803.24	618.14
---	----------	--------

Total Parts (S\$) 11,257.96 2,512.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS	New	500.00	450.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	500.00	400.00
3	TO CHECK WIRING	New	40.00	20.00
4	TO REMOVE,REFIT FRONT BUMPER SENSOR	New	120.00	40.00
Gross Labour Cost (\$\$)			1,160.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >