

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011271/EWY3Q2**Date:** 01/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00135282200

Claimant Vehicle No : SHB3363C**Insured Vehicle No :** SMC1144S

Date of Loss: 08/11/2022

Nature of Claim: TP

Claim No: SNM22D208067/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHB3363C**

Make & Model: TOYOTA PRIUS, 1.5 (A)

Engine No: 2ZR2H18145

Reg. Date: 25/08/2020 (Man. Year: 2020)

Chassis No: JTDKB3FU403092694

Colour: Yellow

Odometer: 306991 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size:

195/55 R15

Front Left Side: Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side:

Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,668.60	7,377.49	3,291.11	30.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	1,840.00	2,210.00	54.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	14,718.60	9,217.49	5,501.11	37.38
+ GST 7.00/7.00% (\$\$)	1,030.30	645.22	385.08	37.38
Nett Amount (\$\$)	15,748.90	9,862.71	5,886.19	37.38

INSPECTION

Date of Assignment: 30/11/2022

Date Inspected: 10/11/2022

Inspected At:

Ding Automotive Pte Ltd (HQ)
31 CORPORATION ROAD
Singapore 649825

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2022)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB3363C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER (DISC 25%)	Broken	521.00 FL	*390.75 F
2	1		*FRONT LH BUMPER TOWING COVER	Not Necessary	30.20 FL	*- F
3	1		*FRONT BUMPER ENERGY ABSORBER (DISC 25%)	Broken	80.20 FL	*60.15 F
4	1		*FRONT BUMPER REINFORCEMENT (DISC 25%)	Dented	716.60 FL	*537.45 F
5	1		*RADIATOR GRILLE (DISC 25%)	Broken	422.50 FL	*316.87 F
6	1		*RADIATOR GRILLE EMBLEM (DISC 25%)	Broken	105.80 FL	*79.35 F
7	1		*RADIATOR GRILLE LOWER NO.1 (DISC 25%)	Cut	178.60 FL	*133.95 F
8	1		*FRONT BUMPER LICENCE PLATE MOULDING (DISC 25%)	Broken	110.50 FL	*82.87 F
9	1		*FRONT LH BUMPER RETAINER (DISC 25%)	Broken	82.30 FL	*61.72 F
10	1		*FRONT BONNET (DISC 25%)	Dented	983.10 FL	*737.32 F
11	1		*FRONT RH BUMPER RETAINER (DISC 25%)	Broken	80.10 FL	*60.07 F
12	1		*FRONT LH HEADLAMP (DISC 25%)	Broken	2,637.60 FL	*1,978.20 F
13	1		*FRONT RH HEADLAMP (DISC 25%)	Broken	2,637.60 FL	*1,978.20 F
14	1		*FRONT BONNET INSULATOR	Not Necessary	410.90 FL	*- F
15	1		*FRONT LH HEADLAMP PANEL (DISC 25%)	Bent	78.90 FL	*59.17 F
16	1		*FRONT RH HEADLAMP PANEL (DISC 25%)	Bent	78.90 FL	*59.17 F
17	1		*RADIATOR GRILLE EMBLEM LOWER COVER (DISC 25%)	Cut	160.50 FL	*120.37 F
18	1		*HORN LH	Not Necessary	134.80 FL	*- F
19	1		*FRONT BONNET LOCK	Not Necessary	135.00 FL	*- F
20	1		*AIR CLEANER INLET NO.3	Not Necessary	42.10 FL	*- F
21	1		*AIR CLEANER INLET NO.2	Not Necessary	112.70 FL	*- F
22	1		*RADIATOR SUPPORT LH SUB-ASSY (DISC 25%)	Bent	245.10 FL	*183.82 F
23	1		*RADIATOR SUPPORT RH SUB-ASSY	Repair	245.10 FL	*- F
24	1		*RADIATOR SUPPORT UPPER SUB-ASSY (DISC 25%)	Bent	377.10 FL	*282.82 F
25	1		*A/C CONDENSER	Not Necessary	1,783.20 FL	*- F
26	1		*FRONT BUMPER UNDERTRAY COVER (SMALL)	Not Necessary	241.90 FL	*- F
27	1		*RADIATOR SUPPORT LOWER SUB-ASSY	Not Necessary	409.90 FL	*- F
28	1		*FRONT RH BUMPER TOWING COVER	Not Necessary	30.20 FL	*- F
29	1		*RADIATOR AIR GUIDE NO.3	Not Necessary	112.70 FL	*- F
30	1		*FRONT BUMPER LOWER ABSORBER	Not Necessary	132.70 FL	*- F
31	1		*FRONT LH BONNET HINGE (DISC 25%)	Bent	58.90 FL	*44.17 F
32	1		*FRONT RH BONNET HINGE (DISC 25%)	Bent	58.90 FL	*44.17 F
33	1		*SET FRONT BUMPER CLIP	Necessary	55.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

12/1/22, 1:18 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*SET FRONT FENDER LINER CLIP	Not Necessary	55.00 FS	*- FS
35	1		*FRONT LICENCE PLATE NUMBER WITH FRAME	Broken	80.00 FS	*40.00 FS
36	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
37	1		*FRONT BUMPER ENGINE UNDER COVER CLIP	Not Necessary	50.00 FS	*- FS
38	1		*SET FRONT BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
39	1		*SET RADIATOR SUPPORT OPENING COVER CLIP	Not Necessary	50.00 FS	*- FS
40	1		*SET RADIATOR GRILLE CLIP	Necessary	50.00 FS	*15.00 FS
41	2		*FENDER EMBLEM LH & RH	Necessary	109.20 FL	*81.90 F
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					14,054.80	7,377.49
- List Item Discount on L Items 25.00/0.00% (S\$)					3,386.20	0.00
Total Parts (S\$)					10,668.60	7,377.49
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	New	1,400.00	800.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	170.00	30.00
3	TO REMOVE AND REFIT A/C CONDENSER ,RADIATOR AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR	New	260.00	0.00
4	TO VACUUM AND TOPUP A/C GAS FOR A/C CONDENSER	New	150.00	0.00
5	TO DIAGNOSTIC ,CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	200.00	30.00
6	TO READJUST AND REALIGN HEADLAMP AIM	New	120.00	30.00
7	TO RESPRAY FRONT BUMPER	New	250.00	200.00
8	TO RESPRAY FRONT BONNET	New	250.00	200.00
9	TO RESPRAY FRONT SUPPORT PANEL	New	250.00	100.00
10	TO RESPRAY FRONT BUMPER TOWING COVER	New	250.00	0.00
11	TO RESPRAY FRONT LH FENDER PANEL	New	250.00	200.00
12	TO RESPRAY FRONT RH FENDER PANEL	New	250.00	200.00
13	TO RESPRAY FRONT BONNET HINGE	New	250.00	50.00
Gross Labour Cost (\$\$)			4,050.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >