

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011293/AQY3E2**Date:** 18/01/2023REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00015482203

**Claimant Vehicle  
No :** SKJ1107L**Insured Vehicle  
No :** CB8231B

Date of Loss: 07/11/2022

Nature of Claim: TP

Claim  
No: SNM22D208049/C02/TAYHPDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKJ1107L**Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17)  
(A)

Engine No: CZDC41890

Reg. Date: 19/11/2021 (Man. Year: 2021)

Chassis No: WAUZZZF31M1131647

Colour: Blue

Odometer: 17143 km

Engine Capacity: 1395 cc

Market Value/New Car  
Price: N/ASum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRES

Front Tyre Size: 215/65 R17

Rear Tyre Size: 215/65 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>          | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                          | 22,885.00         | 11,492.60         | 11,392.40         | 49.78         |
| Miscellaneous Items            | 0.00              | 0.00              | 0.00              |               |
| Labour                         | 9,952.00          | 6,132.00          | 3,820.00          | 38.38         |
| Paintwork Labour               | 0.00              | 0.00              | 0.00              |               |
| Towing                         | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (\$\$)</b>      | <b>32,837.00</b>  | <b>17,624.60</b>  | <b>15,212.40</b>  | <b>46.33</b>  |
| <b>+ GST 8.00/8.00% (\$\$)</b> | 2,626.96          | 1,409.97          | 1,216.99          | 46.33         |
| <b>Nett Amount (\$\$)</b>      | <b>35,463.96</b>  | <b>19,034.57</b>  | <b>16,429.39</b>  | <b>46.33</b>  |

INSPECTION

Date of Assignment: 13/01/2023

Date Inspected: 10/11/2022

Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 18 Jan 2023)                                  |
| <b>Parts:</b>        | M1-SUV                                                                                                                                                                       | AUDI Q3 SPORTBACK 1.4 TFSI S TRONIC (17) (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKJ1107L)                                                                                                                                    |                                                                                |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                                |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                                |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                   | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                                 | Deformed      | 2,018.00 FS | *2,018.00 FS |
| 2   | 1   |          | *FRONT BUMPER CLOSING ELEMENT - RH            | Not Necessary | 66.00 FS    | *- FS        |
| 3   | 1   |          | *FRONT BUMPER TRIM                            | Not Necessary | 396.00 FS   | *- FS        |
| 4   | 1   |          | *FRONT BUMPER GRILLE - CENTER                 | Not Necessary | 242.00 FS   | *- FS        |
| 5   | 2   |          | *FRONT PARKING AID SENSOR SUPPORT - LH / RH   | Not Necessary | 58.00 FS    | *- FS        |
| 6   | 1   |          | *FRONT BUMPER CLOSING ELEMENT                 | Not Necessary | 212.00 FS   | *- FS        |
| 7   | 1   |          | *FRONT BUMPER SPOILER                         | Deformed      | 850.00 FS   | *849.50 FS   |
| 8   | 1   |          | *FRONT BUMPER AIR GUIDE GRILLE - RH           | Not Necessary | 171.00 FS   | *- FS        |
| 9   | 1   |          | *FRONT BUMPER TRIM - RH                       | Not Necessary | 182.00 FS   | *- FS        |
| 10  | 1   |          | *FRONT PARKING AID SENSOR SUPPORT - RH        | Not Necessary | 29.00 FS    | *- FS        |
| 11  | 1   |          | *RADIATOR GRILLE                              | Not Necessary | 2,135.00 FS | *- FS        |
| 12  | 1   |          | *RADIATOR GRILLE STRIKER PLATE                | Not Necessary | 271.00 FS   | *- FS        |
| 13  | 1   |          | *RADIATOR GRILLE COVER                        | Not Necessary | 271.00 FS   | *- FS        |
| 14  | 1   |          | *FRONT BUMPER GUIDE SECTION - RH              | Not Necessary | 43.00 FS    | *- FS        |
| 15  | 1   |          | *FRONT BUMPER FOAM FILLER PIECE               | Not Necessary | 114.00 FS   | *- FS        |
| 16  | 1   |          | *FRONT BUMPER REINFORCEMENT BEAM              | Not Necessary | 974.00 FS   | *- FS        |
| 17  | 1   |          | *FRONT BUMPER TOP COVER                       | Not Necessary | 137.00 FS   | *- FS        |
| 18  | 1   |          | *CAUTION SIGN STICKER                         | Not Necessary | 16.00 FS    | *- FS        |
| 19  | 1   |          | *AIR CONDITIONER STICKER                      | Not Necessary | 9.00 FS     | *- FS        |
| 20  | 1   |          | *FRONT FENDER - RH                            | Dented        | 1,445.00 FS | *1,445.00 FS |
| 21  | 1   |          | *FRONT FENDER ATTACHMENT PARTS                | Not Necessary | 66.00 FS    | *- FS        |
| 22  | 1   |          | *FRONT FENDER BRACE - RH                      | Damaged       | 98.00 FS    | *97.10 FS    |
| 23  | 1   |          | *FRONT FENDER BRACKET - RH                    | Not Necessary | 39.00 FS    | *- FS        |
| 24  | 1   |          | *FRONT FENDER CLOSING ELEMENT - RH            | Not Necessary | 37.00 FS    | *- FS        |
| 25  | 1   |          | *FRONT WHEEL HOUSING LINER - RH               | Not Necessary | 260.00 FS   | *- FS        |
| 26  | 1   |          | *FRONT WHEEL HOUSING LINER COVER - RH         | Not Necessary | 18.00 FS    | *- FS        |
| 27  | 1   |          | *FRONT FENDER CLOSING ELEMENT - RH            | Not Necessary | 22.00 FS    | *- FS        |
| 28  | 1   |          | *FRONT PARKING AID SENSOR                     | Not Necessary | 266.00 FS   | *- FS        |
| 29  | 4   |          | *FRONT PARKING AID SEAL RING                  | Not Necessary | 10.00 FS    | *- FS        |
| 30  | 1   |          | *HEADLIGHT MOUNTING - RH                      | Not Necessary | 132.00 FS   | *- FS        |
| 31  | 1   |          | *HEADLIGHT - RH                               | Cracked       | 5,952.00 FS | *5,952.00 FS |
| 32  | 1   |          | *LIFT CYLINDER - RH                           | Not Necessary | 231.00 FS   | *- FS        |
| 33  | 1   |          | *LIFT CYLINDER HOSE                           | Not Necessary | 92.00 FS    | *- FS        |
| 34  | 2   |          | *FRONT WHEEL COVER - LH / RH                  | Necessary     | 1,132.00 FS | *1,131.00 FS |
| 35  | 1   |          | *RADIATOR AIR GUIDE - RH                      | Not Necessary | 43.00 FS    | *- FS        |
| 36  | 1   |          | *FRONT DOOR - RH                              | Repair        | 3,028.00 FS | *- FS        |
| 37  | 1   |          | *FRONT OUTER DOOR SEAL - RH                   | Not Necessary | 185.00 FS   | *- FS        |
| 38  | 1   |          | *FRONT DOOR CATCH                             | Not Necessary | 134.00 FS   | *- FS        |
| 39  | 1   |          | *FRONT DOOR COVER - RH                        | Not Necessary | 390.00 FS   | *- FS        |
| 40  | 1   |          | *FRONT WINDOW SLOT SEAL TRIM STRIP - RH OUTER | Not Necessary | 251.00 FS   | *- FS        |
| 41  | 1   |          | *FRONT NO PLATE                               | Not Necessary | 60.00 FS    | *- FS        |
| 42  | 1   |          | *SUNDRIES                                     | Not Necessary | 800.00 FS   | *- FS        |

Report was unsubmitted during this print-out.

| No.                          | Qty | Part No. | Particulars | Condition | Repairer's | Amount    |
|------------------------------|-----|----------|-------------|-----------|------------|-----------|
| F=Franchise part. S=SpcNett. |     |          |             |           |            |           |
| Total Parts (S\$)            |     |          |             |           | 22,885.00  | 11,492.60 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                                                   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                               |          |                 |                 |
| 1                               | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID               | New      | 480.00          | 480.00          |
| 2                               | TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE                                                                                           | New      | 400.00          | 400.00          |
| 3                               | TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES                                                        | New      | 400.00          | 280.00          |
| 4                               | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New      | 3,200.00        | 1,600.00        |
| 5                               | TO RESPRAY FRONT BUMPER, FRONT BUMPER, LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS                            | New      | 5,000.00        | 2,900.00        |
| 6                               | TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE                                                                                                                   | New      | 280.00          | 280.00          |
| 7                               | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                                 | New      | 192.00          | 192.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                               |          | <b>9,952.00</b> | <b>6,132.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >