

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011297/UVY3Q2**Date:** 16/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00178422201		
Claimant Vehicle No :	SLX8770P	Insured Vehicle No :	SMN2437H		
Date of Loss:	04/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208061/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX8770P	Engine No:	FB20YC82673
Make & Model:	SUBARU XV, 2.0 I-S EYESIGHT AWD CVT (A)	Chassis No:	JF1GT7KL5JG031633
Reg. Date:	16/04/2018 (Man. Year: 2018)	Odometer:	83832 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,720.96	761.52	959.44	55.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	920.00	1,020.00	52.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,660.96	1,681.52	1,979.44	54.07
+ GST 7.00/7.00% (S\$)	256.27	117.71	138.56	54.07
Nett Amount (S\$)	3,917.23	1,799.23	2,118.00	54.07

INSPECTION

Date of Assignment:	10/11/2022		
Date Inspected:	05/12/2022	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2023)
Parts:	M1-SUV	SUBARU XV 2.0 I-S EYESIGHT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX8770P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	553.40 FL	*553.40 FL
2	2		*REAR BUMPER SIDE HOLDER -LH/RH	Not Necessary	48.60 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
4	1		*REAR BUMPER TOW COVER	Not Necessary	22.70 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	308.70 FL	*308.70 FL
6	2		*REAR BUMPER LAMP -LH/RH	Not Necessary	318.80 FL	*- FL
7	2		*REAR BUMPER INNER LOWER BRACKET -LH/RH	Cracked	54.80 FL	*54.80 FL
8	1		*REAR BOOT RUBBER	Not Necessary	156.70 FL	*- FL
9	1		*REAR END PANEL	Repair	285.70 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Not Necessary	91.80 FL	*- FL
11	1		*SET REAR BUMPER SENSOR	Serviceable	220.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					2,096.20	951.90
- List Item Discount on L Items 20.00/20.00% (\$\$)					375.24	190.38
Total Parts (\$\$)					1,720.96	761.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS	New	800.00	300.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	500.00
3	TO CHECK WIRING	New	40.00	20.00
4	TO REMOVE,REFIT REAR GARNISHES	New	120.00	60.00
5	TO REMOVE,REFIT /REPLACE REAR BUMPER SENSOR	New	120.00	40.00
6	TO TUFF-KOTE	New	60.00	0.00
Gross Labour Cost (S\$)			1,940.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >