



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 1019T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	15.00	15.00
1	NUMBER PLATE WITH HOUSING (SN)	CUT	60.00	60.00
1	FRONT BUMPER (SN)	TO REPAIR SEE LABOUR	1,432.04	-
1	AIR DUCT SEGMENT (SN)	NOT NECESSARY	133.70	-
1	LICENSE PLATE HOLDER (SN)	NOT NECESSARY	134.42	-
1	RAD, CHROME TRIM (SN)	CRACKED	274.53	274.53
1	RAD, PROTECTIVE GRILLE (SN)	NOT NECESSARY	142.12	-
1	BASE PLATE STAR (SN)	NOT NECESSARY	467.63	-
1	RAD, GRILLE CARRIER (SN)	NOT NECESSARY	222.95	-
			2,882.39	349.53
	<u>LABOUR</u>			
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	PANEL BEAT TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,200.00	960.00
	RESPRAY ON FRONT BUMPER AND ACCIDENT AFFECTED AREA.		1,200.00	800.00
			2,780.00	2,140.00
GRAND TOTAL			5,662.39	2,489.53
RECOMMENDED COST OF REPAIRS				2,489.53

Report Ref No. CS/SMR22011298/Evy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.