

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

**Our File No:** CS/AIS22011300/EQY3Q2**Date:** 30/11/2022**REFERENCE**

Insured/Claimant: 800 SUPER WASTE MGMT PTE LTD Policy No: 202222007884/FR  
Date of Loss: 03/11/2022 Nature of Claim: OD Claim No: 202222007884

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **XE4435S**  
Make & Model: MAN TGS 26.320, 10.5 D 6X4 BB (M) Engine No: 50549523914948  
Reg. Date: 03/10/2018 (Man. Year: 2017) Chassis No: WMA26SZZXJM772314  
Colour: White Odometer: 452479 km  
Engine Capacity: 10518 cc  
Market Value/New Car Price: S\$130,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5  
Front Left Side: Firemax 4 mm Rear Left Side: Firemax 4 mm  
Front Right Side: Firemax 4 mm Rear Right Side: Firemax 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,314.51	9,314.51	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Total Labour	1,260.00	1,260.00	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,574.51</b>	<b>10,574.51</b>	<b>0.00</b>	<b>0.00</b>
<b>- Excess (S\$)</b>	<b>4,500.00</b>	<b>4,500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>6,074.51</b>	<b>6,074.51</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>425.22</b>	<b>425.22</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>6,499.73</b>	<b>6,499.73</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment: 10/11/2022

Date Inspected: 11/11/2022 Inspected At:

ST Engineering Land Systems Ltd (HQ)  
31 Corporation Road  
Singapore 649825

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Nov 2022)	
<b>Parts:</b>	N/A	MAN TGS 26.320 10.5 D 6X4 BB (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XE4435S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER HEX COLLAR BOLT (WITH 40% DISCOUNT) (4 PCS)	Necessary	36.89 FL	*36.89 FL
2	2	*HEX LOCK NUT (WITH 40% DISCOUNT)	Necessary	13.76 FL	*13.76 FL
3	1	*VISCO FAN (WITH 40% DISCOUNT)	Bent	2,780.22 FL	*2,780.22 FL
4	1	*COOLING SYSTEM (WITH 40% DISCOUNT)	Broken	4,000.64 FL	*4,000.64 FL
5	1	*BRACKET RADIATOR GUARD RIGHT (WITH 40% DISCOUNT)	Bent	229.36 FL	*229.36 FL
6	1	*BRACKET RADIATOR GUARD LEFT (WITH 40% DISCOUNT)	Bent	229.36 FL	*229.36 FL
7	1	*RADIATOR GUARD PAINTED (WITH 40% DISCOUNT)	Bent	419.08 FL	*419.08 FL
8	1	*BLEEDER LINE (WITH 40% DISCOUNT)	Necessary	94.00 FL	*94.00 FL
9	1	*FAN COWL (WITH 40% DISCOUNT)	Necessary	94.00 FL	*94.00 FL
10	1	*FAN COWLING (WITH 40% DISCOUNT)	Broken	378.02 FL	*378.02 FL
11	2	*SPRING STRUT (WITH 40% DISCOUNT)	Necessary / Bent	933.24 FL	*933.24 FL
12	1	*LIQUEFIER (WITH 40% DISCOUNT)	Bent	594.38 FL	*594.38 FL
13	1	*COOLING WATER HOSE (WITH 40% DISCOUNT)	Necessary	84.02 FL	*84.02 FL
14	1	*SHAPED HOSE (WITH 40% DISCOUNT)	Necessary	40.84 FL	*40.84 FL
15	1	*32L COOLANT FLUIDS	Necessary	352.00 FL	*352.00 FL
16	1	*BLEEDER LINE (WITH 40% DISCOUNT)	Bent	62.68 FS	*62.68 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,342.49</b>	<b>10,342.49</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,027.98</b>	<b>1,027.98</b>
<b>Total Parts (\$\$)</b>	<b>9,314.51</b>	<b>9,314.51</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WITH REPLACE COOLING SYSTEM ,VISCO FAN,CONDENSOR,COOLANT FLUID AND PARTS OF DAMAGED DUE TO CRASH DAMAGED (NOTE:AFTER THIS THIS REPLACEMENT HAVE TO FURTHER CHECK ENGINE CONDITION)	New	1,260.00	1,260.00
2	TO FILL IN CLIMATE REFRIGERANT	New	140.00	140.00
<b>Gross Labour Cost (\$)</b>			<b>1,400.00</b>	<b>1,400.00</b>
<b>- 10.00/10.00% Labour Discount (\$)</b>			140.00	140.00
<b>Gross Labour after Discount (\$)</b>			<b>1,260.00</b>	<b>1,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >