



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 6128G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,422.10	-
1	FRONT DOOR SIDE MIRROR ASSY RH	BROKEN	1,059.20	1,059.20
1	FRONT DOOR SIDE MIRROR SIGNAL LAMP RH	CRACKED	59.20	59.20
1	FRONT DOOR SIDE MIRROR COVER RH	CUT	118.50	118.50
	LESS 25% DISCOUNT		-664.75	-309.23
			1,994.25	927.67
	<b><u>LABOUR</u></b>			
	LABOUR FOR PANEL BEATING & REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH. SPRAY PAINTING.		300.00	280.00
			450.00	300.00
			750.00	580.00
	<b>GRAND TOTAL</b>		<b>2,744.25</b>	<b>1,507.67</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,200.00</b>

Report Ref No. CS/FCI22011305/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.