

Vehicle Damage Assessment Report for [SHC1889K]

Estimate Created: 10/11/2022 10:25 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 29/12/2022 03:04 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Ioniq
Engine Type			
License Plate Number	SHC1889K	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$950.00 WITH 2 DAYS

Insurlogic 5 (29/12/2022 03:02)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER CLIPS		1	22.00	-20.00 %	17.60
REAR BUMPER CENTRE MOULDING ASSY		1	451.25	-20.00 %	361.00
Parts Subtotal					378.60

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER REVERSE SENSOR		1.0	180.00	0.00 %	180.00
Materials Subtotal					180.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING	RnR	350.00	0.00 %	350.00
REMOVE/REFIX REVERSE SENSOR	RnR	30.00	0.00 %	30.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
REAR BUMPER COVER	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING CHARGE	Full spray	250.00	0.00 %	250.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 380.00

Paint Labor Subtotal 250.00

Labor Subtotal 630.00

Summary

Repair Cost	1,188.60
Discount(20 %)	(237.72)
	950.88
Excess	(0.00)
GST(0.00 %)	0.00

Grand Subtotal	950.88
----------------	--------