



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 6670J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	DENTED / DISTORTED	629.00	629.00
1	BONNET LOCK	SERVICEABLE	46.00	-
1	HEADLAMP RH	REFIT	539.00	-
2	FRT GRILLE R/L @\$88.00	DENTED / CRACKED	176.00	176.00
6	FRT GRILLE CLIP @\$2.40	NECESSARY	14.40	14.40
1	FRT GRILLE GARNISH	DENTED / CRACKED	142.00	90.00
1	FRT EMBLEM	NECESSARY	37.00	37.00
1	FRT BUMPER	DENTED	718.00	580.00
1	FRT NO. PLATE GARNISH	DENTED / DEFORMED	35.00	35.00
1	FRT BUMPER AIR DAM (SKIRT)	REFIT	656.00	-
10	FRT BUMPER RIVET @\$2.00	NECESSARY	20.00	20.00
2	FRT BUMPER SIDE RETAINER R/L @\$41.00	DENTED / NECESSARY	82.00	45.00
1	FRT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	616.00	-
1	FRT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
LESS 10% DISCOUNT			-371.04	-162.64
			3,339.36	1,463.76
<u>SPECIAL NETT ITEMS</u>				
1	SET FRT NO. PLATE (W/BRACKET) (SN)	DENTED / CRACKED	50.00	40.00
			50.00	40.00
<u>LABOUR</u>				
TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND FOCUS HEADLAMP.			50.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL RADIATOR, A/C CONDENSER AND PIPINGS FOR NECESSARY REPAIRS. (INCLUDE PRESSURE TEST COOLING SYSTEM AND VACUUM, RECHARGE A/C GAS)	NOT NECESSARY	200.00	-
	TO TRANSFER FRONT BUMPER SKIRT TO NEW BUMPER AND SUPPLY SEALANT / ADHESIVE TAPE.		60.00	30.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT SUPPORT PANEL ASSY AND FRT FENDER RH.		1,000.00	400.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,000.00	600.00
			2,310.00	1,060.00
GRAND TOTAL			5,699.36	2,563.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,050.00

Report Ref No. CS3/SMR22000718/Svy3e2-1

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.