



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5062B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DIPPED BEAM HEADLAMP	MISSING	70.00	70.00
1	MAIN BEAM HEADLAMO	MISSING	67.00	67.00
1	FRT O/S LIGHT BEZEL COMP MOULD-CL 2;FRT	BROKEN	151.00	151.00
1	FRT OS CORNER DEFLECTOR COMP MOULD CL1	BROKEN	155.00	155.00
1	O/S CORNER BUMPER COMP MOULD-CL 1.FRT	BROKEN	230.00	230.00
			673.00	673.00
<u>LABOUR</u>				
	SPRAY PAINT - GREEN;600ML;SG BUS.		30.00	30.00
	SPRAY PAINT - BLACK (PYLOX).		3.00	3.00
	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS / ASSESSMENT BY WORKSHOP.	NOT NECESSARY	188.00	-
	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS BY CONTRACTOR.		950.00	950.00
	TO REMOVE / REPLACE / REPAIR DAMAGE ADVERTISEMENT / GREEN LIVERY PANEL. (NPA)	NOT NECESSARY	-	-
	TOWING COST. (NPA)	NOT NECESSARY	-	-
			1,171.00	983.00
GRAND TOTAL			1,844.00	1,656.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				1,656.00

Report Ref No. CS/LPC22007925/Rcy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.