

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120  
T : (65) 6419 3000  
www.aig.sg

**Claim No:** 0161496872SG **Date of Survey:** 21/12/2021  
**Repairer:** TRANS EUROKARS PTE LTD - TANJONG PENJURU

#### REFERENCE

**Insured:** ALEXIUS CHEW HUI JUN **Policy No:** 2070171356  
**Date of Loss:** 18/12/2021 **Nature of Claim:** OD

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg. No:** SMX6065T  
**Make & Model:** MAZDA 2, 1.5 HATCHBACK STANDARD I4 (A) **Reg. Date:** 21/01/2021  
**Engine No:** P520719247 **Chassis No:** JM6DJ2HAA01400113

#### CONDITION OF TYRES

<b>Front Tyre Size:</b>	185/65R15	<b>Rear Tyre Size:</b>	185/65R15
<b>Front Left Side:</b>	Dunlop 7 mm	<b>Rear Left Side:</b>	Dunlop 7 mm
<b>Front Right Side:</b>	Dunlop 7 mm	<b>Rear Right Side:</b>	Dunlop 7 mm

*The above values represent the remaining tyre treads depth*

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>Footbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No
<b>Handbrake (Serviceable):</b>	Yes	<b>Steering (Serviceable):</b>	Yes
			<b>Pre-accident Condition:</b> Good

#### TOTAL OFFER

<b>Offer Authorized By:</b>	NG, THADDAEUS-HC on 03 Mar 2022 15:25
<b>Offer Initiated By:</b>	NG, THADDAEUS-HC on 21 Dec 2021 16:17
<b>Subrogation:</b>	Yes
<b>Rep. Gross Total:</b>	<b>S\$10,311.84</b> [Diff: S\$4,734.52, 45.91%]
<b>Approved Gross Total:</b>	<b>S\$5,577.32</b>
<b>- Excess:</b>	S\$0.00 [ Waived: S\$600.00 ] [ Remarks: Not Applicable ]
	S\$5,577.32
<b>+ GST (7.00%):</b>	S\$390.41
<b>Approved Nett Amount:</b>	<b>S\$5,967.73</b> (No Betterment/Depreciation)

**Special Remarks:** Damaged parts as require only approval with acknowledgement during physical repair for your attention. Kindly do not hesitate to update resurvey for check and supplementary item

COST OF CLAIMS	Repairer's	Our Offer	Difference	Diff %
Parts	2,731.84	1,702.32	1,029.52	37.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	3,875.00	3,705.00	48.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$)</b>	<b>10,311.84</b>	<b>5,577.32</b>	<b>4,734.52</b>	<b>45.91</b>
<b>+ GST 7.00/7.00% (\$)</b>	<b>721.83</b>	<b>390.41</b>	<b>331.42</b>	<b>45.91</b>

**Nett Amount (S\$)**

**11,033.67**

**5,967.73**

**5,065.94**

**45.91**

---

**SURVEYOR'S REMARKS**

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 5.0 days

Authorised Repair : Yes

Inspection conducted by : Ng, Thaddaeus-HC (AIG Claims Dept)

Signature : \_

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER		893.40 FL	*893.40 FL
2	1		*BRACKET CENTER REAR BUMPER		5.40 FL	Serviceable
3	2		*STAY REAR BUMPER		47.60 FL	Serviceable
4	1		*RETAINER LH REAR		27.20 FL	*27.20 FL
5	1		*SPLASH SHIELD LH REAR		52.10 FL	*52.10 FL
6	1		*FINISHER REAR LH		27.50 FL	Serviceable
7	4		*GROMMET,SCREW		10.80 FL	*10.80 FL
8	1		*BRACKET REAR BUMPER		26.00 FL	*26.00 FL
9	7		*FASTENER		21.00 FL	*21.00 FL
10	1		*TAIL LAMP LH		683.00 FL	*683.00 FL
11	1		*FASTENER,LAMP		15.70 FL	Reuse
12	1		*REAR END PANEL		477.10 FL	Repair
13	1		*REAR FENDER LOWER N0.2		183.60 FL	*183.60 FL
14	1		*REAR FENDER LOWER N0.1		216.90 FL	Repair
15	1		*CHAMBER,EXTRACTOR		49.20 FL	*49.20 FL
16	1		*BODY SIDE MIRROR LH		372.80 FL	Serviceable
17	1		*LAMP SIGNAL TURN LH		123.90 FL	Serviceable
18	1		*COVER SIDE MIRROR LH		128.40 FL	*128.40 FL
19	1		*GLASS&HOLDER LH,MIRROR		53.20 FL	*53.20 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,414.80</b>	<b>2,127.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	682.96	425.58
<b>Total Parts (\$\$)</b>	<b>2,731.84</b>	<b>1,702.32</b>

AIG Asia Pacific Insurance Pte. Ltd./SMX6065T/03/03/2022 15:25

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER, REAR END PANEL , REAR FENDER LOWER LH AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.	New	2,520.00	945.00
2	TO RESPRAY REAR BUMPER.REAR END PANEL, REAR FENDER LOWER LH,REAR FENDER LH, REAR DOOR LH, FRONT DOOR LH AND ALL AREAS AFFECTED BY THE ACCIDENTS.	New	4,200.00	2,400.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING Not Require	New	180.00	0.00
4	TO TRANSFER REVERSE SENSORS .	New	180.00	180.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	200.00	150.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	250.00	180.00
7	SUNDRIES.	New	50.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>7,580.00</b>	<b>3,875.00</b>

AIG Asia Pacific Insurance Pte. Ltd./SMX6065T/03/03/2022 15:25

< END OF REPORT >