

Motor Vehicle Appraiser and Insurance Loss Adjuster

Reliance Appraisal Pte Ltd© 272D, Sengkang Central Singapore 544272 Co. Reg. No. 202214158E Email: info@ra-appraisal.com Tel: (65) 9010 7765

VEHICLE DAMAGE ASSESSMENT REPORT

Attn: RIGHT CLICK AUTOWORKS PTE LTD Adjuster Ref: 202206019
7 Soon Lee Street #01-27 ISPACES Singapore 627608 Date: 26/7/2022

Type of Claim: TP

CLAIM DETAILS

Claim No: Handling Repairer: RIGHT CLICK AUTOWORKS PTE LTD

Claimant Vehicle No: FBJ3822Z Insured Vehicle No: SHF283Z
Claimant: P PUVARASU PERIASAMY @ P PUVARASU S/O PERIASAMY

Date of Loss: 9/6/2022 Policy No: NA

VEHICLE DETAILS

Vehicle No:FBJ3822ZColour:OrangeModel:JUPITER 135 MANUALMake:YAMAHARegistration Date:02/05/2014(Man. Year: 2013)Engine No:55S130852

COE Category: D - Motorcycle Chassis No: MH355S004EK130851

Market Value/ N/A Engine Capacity: 134

New Car Price (S\$):

Sum Insured (S\$): Market Value/New Car Price Odometer (km): 75,732

CONDITION OF VEHICLE DURING INSPECTION

General Condition: Fair Steering: In Order Footbrake: In Order Pre-accident Condition: Good Engine Modification: No Handbrake: In Order

CONDITION OF TYRES

Front Tyre Brand: Pirelli Rear Tyre Brand: Diablo

Front Side: 90/80-17 4mm Rear Side: 80/90 4mm

Front Right Side: - Rear Right Side: -

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer	Adjuster	Difference	Diff%
Part(s)	5,256.70	4,936.70	320.00	6.09
Labour	620.00	370.00	250.00	40.32
Paintwork Labour	600.00	500.00	100.00	16.67
Gross Total (S\$)	6,476.70	5,806.70	670.00	10.34
(Lump Sum) Adjusted Total (S\$)		4,650.00	1,826.70	28.20
- Excess (S\$)	NA	NA	0.00	0.00
Sub Total (S\$)	6,476.70	4,650.00	1,826.70	28.20
+ 7% GST (S\$)	NA	NA	NA	NA
Nett Repair Cost + 7% GST (S\$)	6,476.70	4,650.00	1,826.70	28.20
Nett Liability (S\$)	6,476.70	4,650.00	1,826.70	28.20

INSPECTION DETAILS

Date of Assignment: 23/6/2022 Inspected At: RIGHT CLICK AUTOWORKS PTE LTD

Date Inspected: 23/6/2022 7 Soon Le
Estimated Repair Period: 5.0 day(s) 627608

Surveyed on a "without prejudice" basis

7 Soon Lee Street #01-27 ISPACES Singapore 627608

Adjuster: Ho Too Boon

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reliance Appraisal Pte Ltd© 272D, Sengkang Central Singapore 544272 Co. Reg. No. 202214158E Email: info@ra-appraisal.com Tel: (65) 9010 7765

Adjuster Ref: 202206019

WITHOUT PREJUDICE

Dear Sir,

Re: Third Party Claim For Vehicle Registration No. FBJ3822Z

We refer to your instruction to appraise the above-mentioned vehicle on 23/06/2022 Which was involved in an accident that happen on the 09/06/2022@0430hrs along TPE toward SLE after Tampines Ave 7 Exit.

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. RIGHT CLICK AUTOWORKS PTE LTD for SGD 6476.7 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 5806.7. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 4650 NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 5 days.

In accordance, we have **Not Authorised** the repair to the damaged vehicle and the survey was conducted strictly on a **"WITHOUT PREJUDICE"** basis.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisement schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully, Reliance Appraisal Pte Ltd©

Ho Too Boon Motor Vehicle Appraiser

te Ltd©

Encls.:

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

Recommended Part(s)

L	No	Qty	art N	Description	Condition	Repairer		Adjuster	
	1	1		Front mudguard	Cut/Distorted	155.00	L	155.00	L
	2	1		Font headlamp fairing	Cut	196.00	L	196.00	L
	3	1		Front headlamp bracket	Cut/Distorted	105.00	L	105.00	L
	4	1		Front fork	Distorted	410.00	L	410.00	L
	5	1		Front fork bearing	Necessary	98.00	L	98.00	L
	6	1		Front handle bar	Bent	168.00	L	168.00	L
	7	1		Front handle bar grip (set)	Cut	110.00	L	110.00	L
	8	1		Front handle bar balancer (set)	Cut	95.00	L	95.00	L
	9	1		Front wheel	Warp	480.00	S	350.00	S
	10	1		Front wing mirror arm n/s	Cracked	95.00	L	95.00	L
	11	1		Front wing mirror glass n/s	Bent	68.00	L	68.00	L
	12	1		Front fairing n/s	Cut	420.00	L	420.00	L
	13	1		Rear side fairing n/s	Cut	340.00	Г	340.00	L
	14	1		Side fairing sticker (set)	Necessary	220.00	S	220.00	S
	15	1		Front step pedal	Cut	98.00	L	98.00	L
	16	1		Front step pedal bracket	Bent	195.00	L	195.00	L
	17	1		Rear step pedal n/s	Missing	95.00	L	95.00	L
	18	1		Rear step pedal bracket n/s	Cracked	128.00	L	128.00	L
	19	1		Rear box carrier	Cut	480.00	S	420.00	S
	20	1		Rear box carrier bracket	Bent	220.00	L	220.00	L
	21	1		Rear wheel	Warp	480.00	S	350.00	S
	22	1		Rear wheel bearing	Necessary	140.00	L	140.00	L
	23	1		Rear swing arm	Distorted	650.00	L	650.00	L
Ŀ	=Lis	t Iter	n. N:	-Nett Item. S=Special Nett Item.	Sub Total (S\$)	5,446.00		5,126.00	
					List Item Discount (S\$)	189.30	5%	189.30	5%
				SPRAISE - N	lett Item Discount (S\$)	0.00	0%	0.00	0%
				A STD A FE	+ F Item Margin (S\$)	0.00	0%	0.00	0%
									i

Part(s) Total (S\$)

- Betterment (S\$)

Part(s) Total after Betterment (S\$)

5,256.70

5,256.70

0.00

0%

4,936.70

4,936.70

0.00

0%

Recommended Labour

No	Description	Repairer	Adjuster
1	Labour to align body frame and replace affected damage areas	500.00	300.00
2	To remove & install wire socket, harness to facilitate repairs.	60.00	30.00
3	To replace front & rear rims, balance tyres	60.00	40.00
4	To spray paint on affected areas	600.00	500.00
	Labour Total (S\$)	1,220.00	870.00

	COST OF REPAIRS	Repairer	Adjuster
	Part(s)	5,256.70	4,936.70
	Labour	620.00	370.00
OPRA/S	Paintwork Labour	600.00	500.00
10 (4)	Gross Total (S\$)	6,476.70	5,806.70
LASKA	(Lump Sum) Adjusted Total (S\$)		4,650.00
	- Excess (S\$)	NA	NA
	Sub Total (S\$)	6,476.70	4,650.00
	+ 7% GST (S\$)	453.37	325.50
	Nett Total (S\$)	6,930.07	4,975.50

<END OF ESTIMATE>



Motor Vehicle Appraiser and Insurance Loss Adjuster

Reliance Appraisal Pte Ltd© 272D, Sengkang Central Singapore 544272 Co. Reg. No. 202214158E Email: info@ra-appraisal.com Tel: (65) 9010 7765

INVOICE

To:RIGHT CLICK AUTOWORKS PTE LTDInvoice No.:202206019Attn:7 Soon Lee Street #01-27 ISPACES SingaporeDate:26/7/2022

627608

DESCRIPTION		AMOUNT
Service rendered		
Professional inspe	ction fees	SGD 320.00
Photographs	63 pcs	SGD 63.00
Transport fees		SGD 60.00
Re-inspection fe	es (work in progress, post repair inspection)	SGD 80.00
	Total	SGD 523.00
Singapore Dollars Five Hundred Twenty Three Only		
Registration no.:	FBJ3822Z	
Make/Model:	YAMAHA JUPITER 135 MANUAL	
Our reference:	202206019	
All payments made payee to:-		
Reliance Appraisal Pte Ltd		



for Reliance Appraisal Pte Ltd



RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 1



Photo 2



RELIANCE APPRAISAL Pte Ltd

 Proper
 Precise
 Profesional

 Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 3



Photo 4





Photo 5



Photo 6



RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 7



Photo 8





Photo 9



Photo 10





Photo 11



Photo 12






Photo 13



Photo 14





Photo 15



Photo 16



 Proper
 Precise
 Profesional

 Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 17



Photo 18





Photo 19




Photo 20






Photo 21



Photo 22






Photo 23



Photo 24



RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 25



Photo 26






Photo 27



Photo 28





Photo 29



Photo 30



RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 31



Photo 32





Photo 33



Photo 34





Photo 35



Photo 36





Photo 37



Photo 38





Photo 39



Photo 40





Photo 41



Photo 42





Photo 43



Photo 44






Photo 45



Photo 46





Photo 47



Photo 48





Photo 49



Photo 50





Photo 51



Photo 52





Photo 53



Photo 54





Photo 55



Photo 56



RELIANCE APPRAISAL Pte Ltd

 Proper
 Precise
 Profesional

 Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 57



Photo 58





Photo 59



Photo 60



RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster



Photo 61



Photo 62





Photo 63