

AUTOMOBILE ASSESSMENT REPORT

TO: GLOBAL MOTORSPORT
C/O: GLOBAL MOTORSPORT
53 UBI AVE 1 #01-12 PAYA UBI IND PARK
SINGAPORE 408934

Our Reference: 1217/GM432
Date: 30 JANUARY 2018

ASSESSMENT OF VEHICLE NO. FBM 4980 C
DATE OF LOSS: 30/11/2017

We have carried out a physical assessment of FBM4980C at **GLOBAL MOTORSPORT**, 53 Ubi Ave 1 #01-12 Paya Ubi Ind Park, Singapore 408934, according to your instruction on **06 DECEMBER 2017** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: **FBM 4980 C**
Make & Model: **KYMCO AK550**
Year of Registration: **2017**

Colour: **SILVER**
Mileage: **000000**

Lack of Info
pic not clear
no parts

2. VEHICLE CONDITION

Body Paint: **GOOD**
Steering: **SERVICEABLE**
Foot Brake: **SERVICEABLE**
Parking Brake: **SERVICEABLE**
Modification: **NIL**

3. TYRE PARTICULARS & CONDITION

Front

Make/Size/Thread: **METZELER 120/70 15R - 100%**

Rear

Make/Size/Thread: **METZELER 160/60 15R - 100%**

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the RHS and LHS portion.

5. REMARKS

Market Value: Na
Salvage Value: Na
Repair Limit: Na

Estimated Amount: \$ 8,078.00
Adjusted Amount: \$ 7,708.00 (Lump Sum of \$7,700.00)
Estimated Repair Days: 8 days


Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.



ASSESSMENT REPORT FOR VEHICLE NO. FBM 4980 C - AK550

Chassis : RFBE10000H1600113

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	WIND SHIELD	Cracked <i>X NN</i>	273.00 <i>?X NN</i>	273.00
1	HANDLE BAR	Bent <i>? NN NN</i>	148.00 <i>?X NN</i>	148.00
1	HANDLE BAR TOP COVER	Cracked <i>X NN</i>	24.00 <i>X NN</i>	24.00
1	HANDLE BAR BOTTOM COVER	Cracked <i>X NN</i>	24.00 <i>X NN</i>	24.00
1	RH THROTTLE GRIP	Cut <i>✓ Wf</i>	90.00 <i>/</i>	90.00
1	RH BRAKE LEVER	Bent <i>X NN</i>	234.00 <i>X NN</i>	234.00
1	HEADLAMP COMPLETE LED	Cracked <i>? Sur</i>	1,284.00 <i>? ✓</i>	1,284.00 <i>750</i>
1	HEADLAMP GRILL (METALLIC CHROME)	Cracked <i>✓ Sur</i>	215.00 <i>/</i>	215.00
1	RH FRONT FORK COMPLETE	Bent <i>X R Sur</i>	719.00 <i>X R</i>	719.00 <i>LR \$80</i>
1	FRONT FORK RH COVER	Cut <i>/ Sur</i>	31.00 <i>/</i>	31.00
1	FRONT RIM	Cut <i>R Sur</i>	953.00 <i>R</i>	953.00
1	RH FRONT COVER	Cracked <i>✓ Sur</i>	165.00 <i>/</i>	165.00
1	RH CENTRE COVER	Cracked <i>✓ Sur</i>	88.00 <i>/</i>	88.00
1	RH SIDE SKIRT	Cracked <i>/ Sur</i>	112.00 <i>/</i>	112.00
1	RH PILLION FOOTREST	Cut <i>✓ Sur</i>	25.00 <i>/</i>	25.00
1	MUFFLER COMPLETE	Bent <i>NN</i>	1,735.00 <i>X NN</i>	1,735.00
1	MUFFLER COVER	Bent <i>Sur ✓</i>	112.00 <i>/</i>	112.00
1	RH FRONT WINKER LAMP LED	Cracked <i>✓ Br</i>	173.00 <i>/</i>	173.00
1	LH FRONT WINKER LAMP LED	Cracked <i>? NN</i>	173.00 <i>X NN</i>	173.00

Less 0% discount

Parts Total:

6,578.00	6,578.00
0.00	0.00
6,578.00	6,578.00

ASSESSMENT REPORT FOR VEHICLE NO. FBM 4980 C – AK550

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	Spray painting	500.00	330.00 ✓
2	Labour for repair and replace parts.	1,000.00	800.00 400
3	Fork press		80
Labour Total :		1,500.00	1,130.00
TOTAL (PARTS & LABOUR) \$		8,078.00	7,708.00

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is **\$7,700.00** (SINGAPORE DOLLARS SEVEN THOUSAND SEVEN HUNDRED ONLY)



Amas Ong
Automobile Assessor