

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 4980C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	WIND SHIELD	NOT NECESSARY	273.00	-
1	HANDLE BAR	NOT NECESSARY	148.00	-
1	HANDLE BAR TOP COVER	NOT NECESSARY	24.00	-
1	HANDLE BAR BOTTOM COVER	NOT NECESSARY	24.00	-
1	RH THROTTLE GRIP	CUT	90.00	90.00
1	RH BRAKE LEVER	NOT NECESSARY	234.00	-
1	HEADLAMP COMPLETE LED	SCRATCHED	1,284.00	750.00
1	HEADLAMP GRILL (METALLIC CHROME)	SCRATCHED	215.00	215.00
1	FRONT FORK RH COVER	SCRATCHED	31.00	31.00
1	FRONT RIM	TO REPAIR SEE LABOUR	953.00	-
1	RH FRONT COVER	SCRATCHED	165.00	165.00
1	RH CENTRE COVER	SCRATCHED	88.00	88.00
1	RH SIDE SKIRT	SCRATCHED	112.00	112.00
1	RH PILLION FOOTREST	SCRATCHED	25.00	25.00
1	MUFFLER COMPLETE	NOT NECESSARY	1,735.00	-
1	MUFFLER COVER	SCRATCHED	112.00	112.00
1	RH FRONT WINKER LAMP LED	BROKEN	173.00	173.00
1	LH FRONT WINKER LAMP LED	NOT NECESSARY	173.00	-
	LESS 10% DISCOUNT		-	-176.10
			5,859.00	1,584.90
	SPECIAL NETT ITEMS			
1	RH FRONT FORK COMPLETE (LOCAL REPAIR) (SN)	SCRATCHED	719.00	80.00
			719.00	80.00
	<u>LABOUR</u>			
	SPRAY PAINTING.		500.00	330.00
	LABOUR FOR REPAIR AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT RIM.		1,000.00	400.00
			1,500.00	730.00
	GRAND TOTAL		8,078.00	2,394.90

Report Ref No. CS1/LPM22011319/Svy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,900.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS1/LPM22011319/Svy3m4

//

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator