

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011326/ACP3Q2**Date:** 25/07/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00114592200

Claimant Vehicle No : SJB323P **Insured Vehicle No :** SND1507L

Date of Loss: 08/11/2022 Nature of Claim: TP Claim No: SNM22D208075/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJB323P**

Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: DEM031679

Reg. Date: 30/04/2021 (Man. Year: 2021) Chassis No: WAUZZZF55MA039717

Colour: Black Odometer: 22140 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18

Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,484.00	8,474.30	6,009.70	41.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,632.00	12,852.00	3,780.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,116.00	21,326.30	9,789.70	31.46
+ GST 8.00/8.00% (S\$)	2,489.28	1,706.10	783.18	31.46
Nett Amount (S\$)	33,605.28	23,032.40	10,572.88	31.46

INSPECTION

Date of Assignment: 11/11/2022

Date Inspected: 15/11/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2023)
Parts:	143	AUDI A5 2.0 SB TFSI S TRONIC (DESIGN) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB323P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,609.00 FS	*2,609.00 FS
2	1		*REAR BUMPER SECURING STRIP	Not Necessary	125.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	249.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	276.00 FS	*- FS
5	2		*REAR BUMPER REFLECTOR -LH/RH	Not Necessary	96.00 FS	*- FS
6	1		*REAR OUTER TAIL LIGHT -RH	Not Necessary	1,269.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION -RH UPPER	Cracked	26.00 FS	*25.20 FS
8	1		*REAR BUMPER GUIDE SECTION -RH	Cracked	49.00 FS	*48.80 FS
9	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	531.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
11	1		*REAR SIDE PANEL -RH	Dented	4,076.00 FS	*4,076.00 FS
12	1		*REAR QUARTER WINDOW -RH	Necessary	798.00 FS	*797.50 FS
13	1		*REAR FUEL INSERT	Not Necessary	100.00 FS	*- FS
14	1		*REAR WHEEL HOUSING LINER -RH	Not Necessary	299.00 FS	*- FS
15	1		*ATTACHMENT PARTS	Not Necessary	136.00 FS	*- FS
16	1		*ADHESIVE TAPES	Not Necessary	221.00 FS	*- FS
17	1		*REAR VENT TRIM	Not Necessary	75.00 FS	*- FS
18	1		*REAR ALUMINIUM RIM	Not Necessary	1,889.00 FS	*- FS
19	1		*REAR ALUMINIUM RIM VALVE	Not Necessary	4.00 FS	*- FS
20	1		*REAR PARKING AID SENSOR	Not Necessary	266.00 FS	*- FS
21	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
22	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
23	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
24	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
25	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
26	1		*SUNDRIES	Necessary	500.00 FS	*37.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	14,484.00	8,474.30
-------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION	New	360.00	360.00
2	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER	New	300.00	300.00
3	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES	New	400.00	400.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
5	TO REMOVE AND REINSTALL REAR SEAT ,BACK REST ,HAT TRAY ,CD PILLAR TRIMS ,LUGGAGE COMPARTMENT TRIMS ,DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
6	TO DISMANTLE AND RENEW REAR BUMPER .TO REMOVE AND REINSTALL RHS SILL PANEL TRIM.TO CUT OUT AND WELD RHS REAR FENDER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	6,400.00	4,800.00
7	TO RESPRAY REAR BUMPER,RHS REAR FENDER ,RHS SILL,ROOF CHANNEL,DOOR ENTRANCE ,DRAIN CHANNEL AND REAR END PANELLING	New	5,500.00	3,600.00
8	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			16,632.00	12,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >