

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22011327/UWY3E2**Date:** 16/11/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001960624

Claimant Vehicle No : SLS453J**Insured Vehicle No :** SLM913E

Date of Loss: 10/11/2022

Nature of Claim: TP Claim No: 290481

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLS453J**

Make & Model: TOYOTA WISH, 1.8 CVT (A)

Engine No: 2ZR1968625

Reg. Date: 06/09/2017 (Man. Year: 2017)

Chassis No: JTDGG20W20J007262

Colour: Blue

Odometer: 58994 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,274.50	3,604.67	3,669.83	50.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	1,910.00	1,260.00	39.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,444.50	5,514.67	4,929.83	47.20
Approved Total (Overridden) (\$\$)		4,400.00		
Nett Amount (\$\$)	10,444.50	4,400.00	6,044.50	57.87

INSPECTION

Date of Assignment: 11/11/2022

Date Inspected: 11/11/2022 Inspected At:

GALAXY AUTO CARE PTE LTD (HQ)
13 KAKI BUKIT ROAD 4, #01-23 BARTLEY BIZ
CENTRE
Singapore 417807

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS453J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,309.00 FL	*1,309.00 FL
2	2		*TAILGATE HINGES	Not Necessary	130.00 FL	*- FL
3	2		*TAILGATE ABSORBER	Not Necessary	510.00 FL	*- FL
4	1		*TAILGATE INNER TRIM	Deformed / Cracked	513.00 FL	*368.10 FL
5	1		*TAILGATE WEATHERSTRIP	Twisted	126.00 FL	*126.00 FL
6	1		*TAILGATE LOCK	Dented / Damaged	474.00 FL	*416.80 FL
7	1		*TAILGATE LOCK STRIKER	Not Necessary	76.00 FL	*- FL
8	1		*TAILGATE LOGO	Necessary	56.00 FL	*56.00 FL
9	1		*TAILGATE EMBLEM WISH	Not fitted	64.00 FL	*- FL
10	1		*TAILGATE CHROME GARNISH	Not Necessary	164.00 FL	*- FL
11	1		*TAILLAMP LH	Not Necessary	434.00 FL	*- FL
12	1		*TAILLAMP RH	Not Necessary	434.00 FL	*- FL
13	1		*TAILGATE WIPER MOTOR	Not Necessary	293.00 FL	*- FL
14	1		*TAILGATE WIPER BLADE	Not Necessary	75.00 FL	*- FL
15	1		*TAILGATE WIPER ARM	Not Necessary	45.00 FL	*- FL
16	1		*TAILGATE WINDSCREEN	Not Necessary	526.00 FL	*- FL
17	1		*TAILGATE WINDSCREEN MOULDING	Necessary	185.00 FL	*185.00 FL
18	1		*REAR BUMPER	Distorted	749.00 FL	*596.90 FL
19	1		*REAR BUMPER DAMPER	O/S Bent	390.00 FL	*105.00 FL
20	1		*REAR BUMPER RETAINER	O/S Bent	152.00 FL	*76.00 FL
21	1		*REAR BUMPER REFLECTOR	O/S Cracked	168.00 FL	*68.00 FL
22	1		*REAR END PANEL	Badly Dented	693.00 FL	*542.00 FL
23	1		*REAR END PANEL GARNISH	Twisted	219.00 FL	*219.00 FL
24	1		*SPARE TYRE TOP BOARD	Not Necessary	168.00 FL	*- FL
25	1		*REAR ANTENNA SENSOR	Cracked	693.00 FL	*285.10 FL
26	1		*EXHAUST MOUNTING	Not Necessary	40.00 FL	*- FL
27	1		*REAR NUMBER PLATE	Cracked	90.00 FS	*40.00 FS
28	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
29	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
30	1		*SET REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
31	1		*SET TAILGATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
32	1		*JOINT SEALANT END PANEL	Necessary	120.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,446.00	4,692.90
- List Item Discount on L Items 25.00/25.00% (\$)	2,171.50	1,088.23
Total Parts (\$)	7,274.50	3,604.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	100.00	20.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	50.00
3	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	New	150.00	80.00
4	REMOVE AND REFIT TAILGATE WINDSCREEN	New	150.00	120.00
5	REMOVE AND RENEW REAR EXHAUST	New	150.00	0.00
6	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,200.00	680.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	900.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	60.00
Gross Labour Cost (S\$)			3,170.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >