

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011331/AVP3Q2**Date:** 30/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00056122201	
Claimant Vehicle No :	GBE3880G	Insured Vehicle No :	GBL3178P	
Date of Loss:	10/11/2022	Nature of Claim:	TP	Claim No: SNM22D208112/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE3880G		Engine No:	1KD2560530
Make & Model:	TOYOTA HIACE, 3.0 (A)		Chassis No:	JTFHT02PX00179692
Reg. Date:	19/11/2015 (Man. Year: 2015)		Odometer:	139012 km
Colour:	Silver			
Engine Capacity:	2982 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,258.90	2,175.02	3,083.88	58.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	1,170.00	3,580.00	75.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,008.90	3,345.02	6,663.88	66.58
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	10,008.90	2,600.00	7,408.90	74.02

INSPECTION

Date of Assignment:	11/11/2022	
Date Inspected:	21/11/2022 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Jan 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE3880G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	485.00 FL	*485.00 FL
2	1		*FRONT BUMPER TOWING COVER LH	Not Necessary	25.00 FL	*- FL
3	1		*FRONT BUMPER SIDE GRILLE LH	N/S Cracked	130.00 FL	*65.00 FL
4	1		*FRONT BUMPER SIDE RETAINER	N/S Cracked	360.00 FL	*180.00 FL
5	1		*HEADLAMP	N/S Cracked	1,340.00 FL	*670.00 FL
6	1		*CENTRE GRILLE UPPER COVER	Cracked	227.70 FL	*227.70 FL
7	1		*CENTRE GRILLE LOWER COVER	Not Necessary	383.80 FL	*- FL
8	1		*CENTRE GRILLE BASE	Cracked	696.20 FL	*581.00 FL
9	1		*BONNET	Not Necessary	845.00 FL	*- FL
10	1		*BONNET LOGO	Not Necessary	75.00 FL	*- FL
11	2		*BONNET HINGE	Not Necessary	116.40 FL	*- FL
12	1		*BONNET LOCK	Not Necessary	95.00 FL	*- FL
13	1		*BONNET STOPPER LH	Not Necessary	28.00 FL	*- FL
14	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FL	*- FL
15	1		*FRONT CORNER PANEL LH	Dented	235.00 FL	*235.00 FL
16	1		*FRONT STEP PANEL PANEL LH	Not Necessary	135.00 FL	*- FL
17	1		*FRONT STEP PANEL GARNISH LH	Torn	185.00 FL	*185.00 FL
18	1		*FRONT DOOR PILLAR LH (OUTER)	Repair	495.10 FL	*- FL
19	2		*FRONT DOOR HINGE LH	Not Necessary	190.00 FL	*- FL
20	1		*FRONT DOOR WIRE HOLDER LH	Cracked	138.00 FL	*138.00 FL
21	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
22	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
23	1		*SET CENTRE GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
24	1		*SET FRONT STEP PANEL GARNISH RH CLIP	Necessary	50.00 FS	*20.00 FS
25	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*FRONT WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
27	1		*FRONT DOOR PILLAR SEALANT RH	Not Necessary	80.00 FS	*- FS
28	1		*FRONT DOOR LTA STICKER	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,835.20	2,866.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,576.30	691.68
Total Parts (\$\$)	5,258.90	2,175.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	600.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	0.00
6	REFOCUS HEADLAMP BEAM	New	60.00	0.00
7	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
8	TRANFER FRONT DOOR MECHANISM	New	80.00	0.00
9	REMOVE & REINSTALL FRONT DASHBOARD	New	450.00	0.00
10	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			4,750.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >