

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	HSBC LIFE (SING	Ref		CS3/ASM22011333/Gqp3e2		
		EVARD #48-01 MARINA BAY RE TOWER 2 SINGAPORE	Date	e:	06/03/2023	
	ATTN: HO WINNIE		Cod	e:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 6271C	Veh. Inspected		FBM 5145R	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M04EEW	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		11/11/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	KYMCO XCITING 400I	c.c	;	399	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	RFBD61011H2100101	Colour		RED	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/70-15	PIRELLI		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	150/70-14	PIRELLI		5 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORT O/S AND N/S BODY.			Œ		
5.	General Information					
	Accident Date	05/11/2022	Inspect Date / Time)	11/11/2022 (05:30 PM)	
	Survey held at	SPEEDY MOTOR CYCLE SERV	ICE CENTRE			
	BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
	Report Ref No. CS3/ASM22011333/Gqp3e2					

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor